

MORRISON HERSHFIELD



Arbor Terrace Community 2018/2019 Reserve Study Update



Presented to:

Arbor Terrace Homeowners Association Sherwood, Oregon

TABLE OF CONTENTS

Page	
SCOPE OF SERVICES & BACKGROUND DOCUMENTATION3	1.
MH PROJECT TEAM4	2.
RESERVE STUDY ANALYTICAL METHODOLOGIES5	3.
ALL LOTS – APPROVED FUNDING PLAN8	4.
APPENDIX A: TABLE 3: SHARED COMMON ELEMENTS LIST14	
APPENDIX B: TABLE 4: DETAILED CASH FLOW22	
APPENDIX C: FIVE YEAR EXPENDITURE OUTLOOK27	
ROWHOMES - FUNDING SCENARIOS29	5.
APPENDIX D: TABLE 3: SHARED COMMON ELEMENTS LIST, (SCENARIO ONE)35	
APPENDIX E: TABLE 4: DETAILED CASH FLOW, (SCENARIO ONE)40	
APPENDIX F: FIVE YEAR EXPENDITURE OUTLOOK, (SCENARIO ONE)43	
APPENDIX G: TABLE 3: SHARED COMMON ELEMENTS LIST, (SCENARIO TWO)48	
APPENDIX H: TABLE 4: DETAILED CASH FLOW, (SCENARIO TWO)53	
APPENDIX I: FIVE YEAR EXPENDITURE OUTLOOK, (SCENARIO TWO)56	
TAMARACK SFH - APPROVED FUNDING PLAN58	6.
APPENDIX J: TABLE 3: SHARED COMMON ELEMENTS LIST64	
APPENDIX K: TABLE 4: DETAILED CASH FLOW67	
APPENDIX L: FIVE YEAR EXPENDITURE OUTLOOK70	
SUMMARY72	7.
APPENDIX M: LIMITATIONS73	

1. SCOPE OF SERVICES AND BACKGROUND DOCUMENTATION

Morrison Hershfield (MH) was retained to conduct a reserve study of the shared common elements owned by the Arbor Terrace Homeowners Association, (ATHOA) for their 2018/2019 fiscal year. The work undertaken by MH was in general conformance with our proposal dated September 20, 2017, issued to and signed by Ms. Amy Boyle, Arbor Terrace Homeowners Association Board President and Treasurer. As per the direction of the agreement MH did perform a physical analysis of the shared common elements for this year's update.

The objective of this RS is to provide a realistic assessment of the monetary reserves required to undertake the necessary repairs or replacements of the shared common element as dictated by their estimated life spans. This RS is designed to be in conformance with "Oregon Revised Statute 100.175" and the ATHOA's governing documents.

The following information, documentation and communication were used to assist in completing the 2018/2019 RS update:

- General & Financial Information, As Provided By:
 - Ms. Amy Boyle, Board President & Treasurer
- Previous Years' Reserve Studies:
 - Fiscal Year 2015/2016 Completed by MH
- Meetings:
 - Onsite Meeting September 12, 2017
 - o Field Assessment October 28, 2017
 - o RS Review Meeting @ MH's Portland Office March 14, 2018

2. MH PROJECT TEAM

Morrison Hershfield has over sixty years of Architectural and Engineering experience within the Buildings and Facilities industry. Our resume' includes designs for new construction along with the rehabilitation of existing buildings. MH has sixteen offices located throughout the United States and Canada with a staff of over 800, consisting primarily of design and engineering professionals.

The following personnel from our Portland Oregon office were assigned to complete your RS:

- Bryan Costa, PE Senior Building Science Consultant
 - Reserve Study Client References:
 - Quayside Condominium Sellwood, OR
 - The VAUX Condominium Portland, OR
 - Arbor Station Townhomes Sherwood, OR
 - Courtyard at Springville Beaverton, OR
 - Memberships and Licenses:
 - Professional Engineer
 - Community Association Institute, (CAI Portland)
 - Portland Building Enclosure Council (Portland BEC)
 - Oregon Washington Community Association Managers (OWCAM)

3. RESERVE STUDY ANALYTICAL METHODOLOGIES

The financial data provided within this year's RS will enable the Association to plan long term, (30 years) when budgeting for the replacement of their shared common elements, as opposed to the higher risk year-to-year, short term approach. There are several different funding methods typically used by HOA's when planning their reserves. Below is a list and descriptions of the more commonly used strategies:

- **Full Funding** The goal of this funding strategy is to attain and maintain the reserves at or near 100 percent. For example, if the association has a component with a tenyear life and a \$5,000 replacement cost, it should have \$1,500 set aside for its replacement after three years, (\$5,000 divided by 10 years = \$500 per year X 3 years = \$1,500). In this example, \$1,500 equals full funding.
- Baseline Funding The goal of this funding method is to keep the reserve cash balance above zero. This means that while each individual component may not be fully funded, the reserve balance does not drop below zero during the projected period. An association using this funding method should understand that any reduction in a component's remaining useful life can result in a deficit in the reserve's cash balance.
- Threshold Funding This method is based on the baseline-funding concept.
 However, the minimum reserve cash balance in threshold funding is set at a
 predetermined dollar amount and is to remain at or above this amount for the entire
 30 years.

For this year's study a "Baseline Funding" method was used so sufficient reserves are maintained within each reserve account, and to ensure an annual closing balance at or above \$0 for the 30-year duration of this study.

The following information was provided by the Association:

- Fiscal Year Duration:
 - July 1, 2018 to June 30, 2019
- Estimated Reserve's Account Balances as of July 1, 2018:
 - o All Lots = \$171,327
 - o Rowhomes = \$191,000
 - Tamarack SFH = (\$25,000)
- Estimated Annual Contributions to the Reserves for 2018/2019:
 - All Lots = \$28,800
 - Rowhomes:
 - Scenario 1 = \$63,960
 - Scenario 2 = \$63,960
 - Tamarack SFH = \$18,900

- Annual "Earned Interest Rate", (EIR): Per the direction of the Association the assumed annual EIR that will be applied to the reserve's account balance will be set at 1.0% (percent). The interest earned on the reserves for each year is based on a Mid-Year Interest Calculation. With the Mid-Year Interest Calculation, the interest earned is calculated at the middle of the fiscal year assuming that half the expenses have been taken out and half the annual contributions have been deposited into the reserves' account.
- Assumed "Average Inflation Rate", (AIR): An annual increase of 2.0% (percent) will be applied to account for the estimated annual rate increases to the shared common elements' renewal costs. The increase will cover the assumed "Inflation Rate" of 2.0% (percent) used over the 30-year period of this study. The inflation rate in the United States at the end of the month of March 2018 was recorded at 2.4% (percent) as per the Consumer Price Index published monthly by the U.S. Labor Department.

The following two tables can be found in Chapters 4, 5 and 6. These two tables will summarize each of the funding paths this study has prepared for each of three entities within the Arbor Terrace Community:

- Table 1: Cash Flow Table: Information found here provides a snapshot of the key financial data for each year. Yearly information includes, total contributions and expenditures, annual rate increases, as well as the beginning and closing balances within the reserve accounts. In short, Table 1 is a simple, easy to use tool that summarizes how much money is estimated to be within the reserves during the 30-year scope of this study.
- Table 2: Cash Flow Chart: Table 2 provides a visual representation of the annual reserve balance, expenses and contributions for each scenario throughout the 30year life of this study.

Opinions of probable cost are provided only as an indication of possible cost for remedial work. The repair or replacement costs are based on published construction cost data, recent bid prices on similar work, and information provided by the owner or their representatives. The opinions of probable cost we have presented can vary due to a number of reasons including changing market conditions, availability of newer materials and systems, and increased or decreased scope of work than we had identified. More precise estimations of probable cost would require a more detailed investigation to define the scope of work.

The repairs and replacements we have forecasted do not represent a fixed schedule for any given element or component reviewed. Such repairs or replacements may be required sooner or later than have anticipated. It should also be noted that these repairs and replacements may not all take place within one year's time and may not be required at all. However, it is prudent to budget for such repairs since failure of some components is somewhat unpredictable. The estimated service life assigned to each item assumes proper maintenance is conducted. Lack of maintenance will result in a decreased service life of various components.

2018/2019 Reserve Study Update Arbor Terrace

MH recommends that the Association utilize the services of a 3rd party consultant when faced with the renewal of components that are categorized as complex or have a significant cost associated with their replacement. These design or engineering professionals will identify irregularities typically before any work begins, minimizing their client's exposure to unnecessary risks and ultimately saving them time and money. They should be actively involved in all phase of the rehabilitation process, (Design, Bidding, and Construction Administration). MH cautions the Association from taking on these responsibilities themselves.


4. FUNDING ALTERNATIVES - ALL LOTS

Summary of Data & Results

Property Name	Arbor Terr	race Community - All Lots
Entity Name		Arbor Terrace HOA
Current Date		June 14, 2018
Year Built, (Conversion Year)		2007
Starting Year, (Forecasted Fiscal Year)		2018
Dollar Year, (Current Fiscal Year)		2018
Fiscal Year Start Date		July 1, 2018
Fiscal Year End Date		June 30, 2019
Assumed Inflation Rate		2.00%
Earned Interest Rate		1.00%
Estimated Starting Balance		\$171,327
Number of Units		160
Approved Funding Plan		
Current Yearly Contribution:	\$	28,800
Monthly Contribution, (Per Unit "Average" For Year One):	\$	15
Lowest Annual Closing Balance	\$	23,589
Largest Annual Closing Balance	\$	367,259
30-Year Closing Balance	\$	304,646
Consulting Allowance		70/

Consulting Allowance 7%

Arbor Terrace Community - All Lots - Funding Graph #1 - FINAL



Approved Funding Path's 30 Year Ending Balance: \$304,646 Op Op A OC c₃₀ Arbor Terrace Community - All Lots - Funding Graph #2 - FINAL 0407 **ANNUAL ENDING BALANCE CHART** 802 802 *_{CO2} c₅₀₂ 0502 ₆0/2 ₉% * * OS 502 0202 8/05 \$300,000 \$250,000 \$200,000 \$150,000 \$100,000 \$400,000 \$50,000 \$0 \$350,000 Yearly Ending Balance for Each Scenario

All Lots - Approved Funding Plan

The following funding plan has been designed and approved by the Association's Board of Directors for this year's update, (2018/2019 Fiscal Year). The starting account balance within the reserves at year one will be approximately \$171,327 with an annual contribution of \$28,800, (figures were provided by Ms. Amy Boyle). All rate increases to the reserve's annual contributions have also been established by the Association's Board of Directors, (BOD).

Analysis

The amount of funds within the reserve's account will maintain a positive balance over the next 30 years, (July 1, 2018 through June 30, 2048). This is contingent on the Association following the funding plan and the scheduled annual increases to the contributions that they have established within this RS over this same period of time. This will also be impacted on how well they maintain and care for their shared common elements.

The chart below shows the three largest renewal periods over the 30-year scope set by this study:

<u>Year</u>	Major Renewal Task	Est. Cost
2032/2033	Vinyl Fencing Replacement	\$80K
2034/2035	Major Landscaping Project	\$200K
2037/2038	Tot-Lot Play Equipment & Gazebo Renewals	\$170K

Please note, that the forecasted repairs and replacements do not represent a fixed schedule for any given element or component reviewed. Such repairs or replacements may be required sooner or later than we have anticipated. It should also be noted that these repairs and replacements may not all take place within one year's time and may not be required at all. However, it is prudent to budget for such repairs since failure of some components is somewhat unpredictable.

Results

This funding plan as approved by the Association will maintain an amount greater than \$0, (Baseline Funding) over the 30-year term set by this RS. MH can recommend this funding plan because it provides the necessary amount of available funds to cover all of the Association's future anticipated replacement needs in terms of their shared common elements.


Annual contributions within this funding plan have been aligned with the list of shared common elements shown in Appendix A, Table 3, (assuming the expenditure is scheduled to be replaced by June 30, 2048). The ensuing two documents, (Table 1 & Table 2) illustrate what the Association should anticipate over the next 30 years should they follow this funding path. For a detailed breakout of the anticipated cash flow for this funding plan see Appendix B, Table 4.

Arbor Terrace Community - All Lots Approved Funding Plan <u>Table 1: Cash Flow Summary</u>

Current Yearly Contribution:\$28,800Monthly Contribution, (Per Unit "Average" For Year One):\$15Assumed Interest Rate1.00%Assumed Inflation Rate2.00%Reserve's Starting Balance as of July 1, 2018\$171,327Reserve's Minimum Annual Ending Balance Within 30 Year Scope\$23,589

#	Year	Annual Opening Balance	Annual Contribution	Annual Rate Increase	Other Contributions	Estimated Annual Expenditures	Projected Earned Interest	Annual Closing Balance
1	2018/2019	\$171,327	\$28,800	-20.2%	\$0	\$15,468	\$1,780	\$186,439
2	2019/2020	\$186,439	\$28,800	0.0%	\$0	\$15,777	\$1,930	\$201,391
3	2020/2021	\$201,391	\$28,800	0.0%	\$0	\$16,093	\$2,077	\$216,176
4	2021/2022	\$216,176	\$28,800	0.0%	\$0	\$20,129	\$2,205	\$227,052
5	2022/2023	\$227,052	\$28,800	0.0%	\$0	\$19,990	\$2,315	\$238,176
6	2023/2024	\$238,176	\$34,560	20.0%	\$0	\$17,078	\$2,469	\$258,128
7	2024/2025	\$258,128	\$34,560	0.0%	\$0	\$17,419	\$2,667	\$277,935
8	2025/2026	\$277,935	\$34,560	0.0%	\$0	\$17,768	\$2,863	\$297,591
9	2026/2027	\$297,591	\$34,560	0.0%	\$0	\$19,002	\$3,054	\$316,203
10	2027/2028	\$316,203	\$34,560	0.0%	\$0	\$45,280	\$3,108	\$308,591
11	2028/2029	\$308,591	\$39,744	15.0%	\$0	\$22,695	\$3,171	\$328,811
12	2029/2030	\$328,811	\$39,744	0.0%	\$0	\$23,149	\$3,371	\$348,777
13	2030/2031	\$348,777	\$39,744	0.0%	\$0	\$39,465	\$3,489	\$352,546
14	2031/2032	\$352,546	\$39,744	0.0%	\$0	\$28,612	\$3,581	\$367,259
15	2032/2033	\$367,259	\$39,744	0.0%	\$0	\$116,085	\$3,291	\$294,209
16	2033/2034	\$294,209	\$45,706	15.0%	\$0	\$25,057	\$3,045	\$317,902
17	2034/2035	\$317,902	\$45,706	0.0%	\$0	\$223,857	\$2,288	\$142,039
18	2035/2036	\$142,039	\$45,706	0.0%	\$0	\$26,070	\$1,519	\$163,193
19	2036/2037	\$163,193	\$45,706	0.0%	\$0	\$26,591	\$1,728	\$184,036
20	2037/2038	\$184,036	\$45,706	0.0%	\$0	\$207,185	\$1,033	\$23,589
21	2038/2039	\$23,589	\$52,561	15.0%	\$0	\$24,545	\$376	\$51,982
22	2039/2040	\$51,982	\$52,561	0.0%	\$0	\$25,036	\$657	\$80,165
23	2040/2041	\$80,165	\$52,561	0.0%	\$0	\$28,443	\$922	\$105,206
24	2041/2042	\$105,206	\$52,561	0.0%	\$0	\$32,749	\$1,151	\$126,170
25	2042/2043	\$126,170	\$52,561	0.0%	\$0	\$29,785	\$1,376	\$150,322
26	2043/2044	\$150,322	\$60,446	15.0%	\$0	\$25,459	\$1,678	\$186,987
27	2044/2045	\$186,987	\$60,446	0.0%	\$0	\$25,968	\$2,042	\$223,507
28	2045/2046	\$223,507	\$60,446	0.0%	\$0	\$26,487	\$2,405	\$259,870
29	2046/2047	\$259,870	\$60,446	0.0%	\$0	\$27,017	\$2,766	\$296,064
30	2047/2048	\$296,064	\$60,446	0.0%	\$0	\$54,852	\$2,989	\$304,646
						\$1,243,110		

Arbor Terrace Community - All Lots Approved Funding Plan <u>Table 2: Cash Flow Chart</u>



APPENDIX A

TABLE 3: SHARED COMMON ELEMENTS LIST - ALL LOTS

This table provides a list of the shared common elements that includes information such as each component's quantities, dates of initial installation or renewal, and estimated unit costs. In addition, this table includes a list of brief comments or recommendations for each corresponding item. MH recommends that close attention be maintained for systems that have an "elevated maintenance" requirement. These components are typically exposed to conditions where they are unlikely to fulfill their usual service life. However it should be noted that in some instances a heightened maintenance plan can maximize the component's serviceable life span. Where a specific material, component or assembly could not be verified during our review, we have assumed the components are suitable for their intended use. Estimated replacement costs are based on current year dollars, (2018).

Arbor Terrace Community - All Lots

Item # Item Description	Component Caption	Estimated Life Expectancy	Assumed Year of Acquisition	Present Age as of 2017	Fetimated Life		Number of Annual Phases *	Quantity	Units of Measure	Unit Cost	Add 3rd Party Consultant Fee (Y/N) Current Estimated Replacement Costs **	Comments/Recommendations
SHARED COMMON ELEMENTS #1: TRACT "D", (PARK AREA ADJACENT TO SW BALER WAY)												
Sub-Category #1: Tot-Lot												
01 42" Metal Fencing & Gates @ Front Elev Refinishing, (Maintenance Task)	photo Pending	10	2007	11	12	12	1	250	Ln. Ft.	\$7.50	N \$1,880	Observed Conditions/Recommended Actions: Early signs of corrosion were identified at selection locations where paint finish was either blistering or had been fully removed. It is recommended these areas be treated and refinished within the next year to prevent further deterioration. Note: The Association has instructed that the scheduled renewal date for this line item will take place 10 years after the metal railing has beer replaced, (See Item #02 for scheduled replacement of the metal railing) Estimated values are based on a field applied finish.
02 42" Metal Fencing & Gates @ Front Elev Replacement, (Renewal Task)	Photo Pendind	25	2007	11	-2	12	1	250	Ln. Ft.	\$50	N \$12,500	Observed Conditions/Recommended Actions: Early signs of corrosion were identified at selection locations where paint finish was either bilstering or had been fully removed. It is recommended these areas be treated and refinished within the next year to prevent further deterioration. Note: The Association has instructed that the scheduled renewal date for this line item will take place in 2030.
03 Concrete Pathways	Photo Penting	50	2007	11	-50	0	50	1,480	Sq. Ft.	\$10	N \$14,800	Observed Conditions/Recommended Actions: Apart from a few minor cracks in a handful of areas, this component appears to be performing as intended. It has been assumed that the replacement of this component would be addressed on an "As Needed" basis and would take place over an extended period of time.
04 Park Benches	Photo Pending	20	2007	11	0	9	1	4	EA	\$1,000	N \$4,000	Observed Conditions/Recommended Actions: Components appear to b in good condition. It is recommended that this equip be power washed annually as part of the general maintenance plan. Follow manufacture requirements when cleaning or refinishing.
05 Play Equipment	Photo Pending	30	2007	11	0	19	1	1	EA	\$30,000	N \$30,000	Observed Conditions/Recommended Actions: Observed a few areas where the paint finish my be reaching the end of it's service life. It is recommended that this equip be power washed annually as part of the general maintenance plan. Follow manufacture requirements when cleaning or refinishing.

^{*} Quantity of years needed or scheduled to complete the renewal process.

^{**} Renewal costs listed are the current values should the scheduled replacement take place the year this RS was completed...

Arbor Terrace Community - All Lots

Table 3: Shared Common Elements List - Replacement Cost Estimates Are Based On Current Year Dollars, (2018)

Table 3: Shared Common Elements List - Replacement Cost Estimates Are Based O	Component Caption	Estimated Life Expectancy	Assumed Year of Acquisition	Present Age as of 2017	Estimated Life	Estimated Time To First Replacement	Number of Annual Phases *	Quantity	Units of Measure	Unit Cost	Add 3rd Party Consultant Fee (Y/N)	Current Estimated Replacement Costs **	Comments/Recommendations
Sub-Category #2: Gazebo		1										0.000	
06 Concrete Pathways	Photo Pandino	50	2007	11	-30	9	20	100	Sq. Ft.	\$10	N	\$1,000	Observed Conditions/Recommended Actions: Apart from a few minor cracks in a handful of areas, this component appears to be performing as intended. It has been assumed that the replacement of this component would be addressed on an "As Needed" basis and would take place over an extended period of time.
07 Concrete Slab/Foundation	Photo Pandino	50	2007	11	0	39	1	624	Sq. Ft.	\$15	N	\$9,360	Observed Conditions/Recommended Actions: No visible cracks or sign of failure to the concrete slab were observed. No action at this time, (p the 2018/2019 RS update, Lvl 2)
08 Stone Column Bases	Photo Panding	25	2007	11	-5	9	1	8	Each	\$1,200	Y	\$10,270	Observed Conditions/Recommended Actions: Efflorescence was observed in multiple locations on the surface of the stone veneer for each of the column bases. The stone veneer and grout at the column bases appear to be in good shape, however it is recommended that regular cleaning be administered to remove the powdery deposit to prevent the risk of deterioration to these components that could lead to an accelerated renewal cycle. Note: There are a few of the 6x6 wooden posts that run through the center of these columns that are showing advanced signs of deterioration. It is recommended these posts be removed this year. Discuss with your contractor if it is possible to reuse the stone veneer a oppose to replacing it.
09 Structure	PhotoParding	30	2007	11	0	19	1	1	Each	\$75,000	N	\$75,000	Observed Conditions/Recommended Actions: There are clear signs of rot that were observed on a few of the 6x6 vertical posts that support the structure. It is recommended that these posts be replaced this fiscal year. This work is currently classified as a "maintenance task" and fun necessary for this repair will drawn against the Operating Budget. It is recommended that the Association conduct a visual review of the wood components as part of their annual maintenance plan.
10 T&G Soffit, (Ventilated)	Photo Pardind	30	2007	11	0	19	1	1,000	Sq. Ft.	\$10	N	\$10,000	Observed Conditions/Recommended Actions: Components appear to in good condition. No action required at this time, (per the 2018/2019 RS Update, Lvl 2)
11 Park Benches, (Attached)	Photo Pandino	20	2007	11	0	9	1	2	Each	\$1,000	N	\$2,000	Observed Conditions/Recommended Actions: Some of the paint finish has been stripped away, exposing raw wood materials. Do to the frequent use these components are likely to endure on an annual basis it is recommended touch paint be applied to the areas where the wood has been exposed annually.

^{*} Quantity of years needed or scheduled to complete the renewal process.

^{**} Renewal costs listed are the current values should the scheduled replacement take place the year this RS was completed...

Arbor Terrace Community - All Lots

Item#	ments List - Replacement Cost Estimates Are Based On	Component Caption	Estimated Life Expectancy	Assumed Year of Acquisition	Present Age as of 2017		Estimated Time To First Replacement	Number of Annual Phases *	Quantity	Units of Measure	Unit Cost	Add 3rd Party Consultant Fee (Y/N)	Current Estimated Replacement Costs **	Comments/Recommendations
12 HOA Bulletin Board, (Free Standi	ng)	Photo Pending	15	2011	7	0	8	1	1	Each	\$750	N	\$750	Observed Conditions/Recommended Actions: Appears to be in good condition. No action required at this time, (per the 2018/2019 RS Update, Lvl 2)
13 Roofing, (Asphaltic Roof Shingles	s)	Photo Pending	25	2007	11	0	14	1	1,000	Sq. Ft.	\$5	N	\$5,000	Observed Conditions/Recommended Actions: Appears to be in good condition. Apart from the scheduled maintenance task recommendations and requires, no action is required at this time, (per the 2018/2019 RS Update, Lvl 2)
14 Refinishing, (Painting & Staining)		Photo Pelling	10	2007	11	3	3	1	1	Each	\$3,500	N	\$3,500	Observed Conditions/Recommended Actions: Appears to be in good condition. As a suggestion, the Association may consider adding power washing of the surface area of the gazebo's various components to their annual maintenance plan. This maintenance task can help to prolong the useful life cycle of the paint finish as well as the structure.
Sub-Category #3: Misc. Components														
15 Vinyl Fence, (42" Tall)		Photo Pending	25	2007	11	0	14	1	465	Ln. Ft.	\$30	N	\$13,950	Observed Conditions/Recommended Actions: Appears to be in good condition. As a suggestion, the Association may consider adding an annual power washing of the fence as part of the scheduled maintenance. This maintenance task can help to prolong the useful life cycle of this component.
16 Concrete Pathways		photo Pending	50	2007	11	-50	0	50	1,800	Sq. Ft.	\$10	N	\$18,000	Observed Conditions/Recommended Actions: Apart from a few minor cracks in a handful of areas, this component appears to be performing as intended. It has been assumed that the replacement of this component would be addressed on an "As Needed" basis and would take place over an extended period of time.

^{*} Quantity of years needed or scheduled to complete the renewal process.

^{**} Renewal costs listed are the current values should the scheduled replacement take place the year this RS was completed..

Arbor Terrace Community - All Lots

Table 3: Shared Common Elements List - Replacement Cost Estimates Are Based On Item # Item Description	Component Caption	Estimated Life Expectancy	Assumed Year of Acquisition	Present Age as of 2017	Adjustment To Estimated Life Expectancy	To First	Number of Annual Phases *	Quantity	Units of Measure	Unit Cost	Add 3rd Party Consultant Fee (Y/N)	Current Estimated Replacement Costs **	Comments/Recommendations
SHARED COMMON ELEMENTS #2: FENCING													
Sub-Category #1: Wood Fencing													
17 6' Cedar Fence, (Good Neighbor Style)	Photo Pandind	15	2017	1	0	14	1	156	Ln. Ft.	\$41	N	\$6,400	Observed Conditions/Recommended Actions: This component was just replaced in 2017. Note: The Association has instructed that they will no longer be refinishing the wood fencing located throughout the community. However they intend to add a maintenance task for regular scheduled cleaning. Funds required for this task will be drawn from the Operating Budget.
Sub-Category #2: Vinyl Fencing													
18 Vinyl Fence, (42" Tall)	Photo Pendind	25	2007	11	0	14	1	1,487	Ln. Ft.	\$30	N	\$44,610	Observed Conditions/Recommended Actions: Appears to be in good condition. As a suggestion, the Association may consider adding an annual power washing of the fence as part of the scheduled maintenance. This maintenance task can help to prolong the useful life cycle of this component.
SHARED COMMON ELEMENTS #3: CONCRETE PATHWAYS & RETAINING WALLS													
Sub-Section #1: Concrete Sidewalks, (5' Wide, w/Attached Curb & Gutter)													
19 SW Holland Lane	Proto Pending	50	2007	11	-50	0	50	18,840	Sq. Ft.	\$10	N	\$188,400	Observed Conditions/Recommended Actions: Observed a few location where the concrete was breaking down and could require replacement as soon as this year, (2018/2019). For all other locations it has been assumed that the replacement of this component would be addressed an "As Needed" basis and would take place over an extended period o time. Locations: SW Holland Lane SW Window Lane SW Silo Terrace SW Bronner Lane
Sub-Section #2: Concrete Sidewalks, (5' Wide, w/Detached Curb & Gutter)													
20 SW Harvester Lane	Proto Perding	50	2007	11	-50	0	50	18,432	Sq. Ft.	\$10	N	\$184,320	Observed Conditions/Recommended Actions: Observed a few location where the concrete was breaking down and could require replacement as soon as this year, (2018/2019). For all other locations it has been assumed that the replacement of this component would be addressed an "As Needed" basis and would take place over an extended period o time. Locations: SW Harvester Lane SW Massey Terrace SW Ferguson Terrace SW Fallow Terrace SW Baler Way
Sub-Section #3: Misc. Concrete & Asphalt Pathways													
21 Concrete Pathways, (4' Wide, No Curb or Gutter)	PhotoPending	50	2007	11	-50	0	50	800	Sq. Ft.	\$10	N	\$8,000	Located at various areas within the community. Observed Conditions/Recommended Actions: Apart from a few minor cracks in a handful of areas, this component appears to be performing as intended. It has been assumed that the replacement of this component would be addressed on an "As Needed" basis and would take place over an extended period of time.

^{*} Quantity of years needed or scheduled to complete the renewal process.

^{**} Renewal costs listed are the current values should the scheduled replacement take place the year this RS was completed..

Arbor Terrace Community - All Lots

Table 3: Shared Common Elements List - Replacement Cost Estimates Are Bas	Component Caption	Estimated Life Expectancy	Assumed Year of Acquisition	Present Age as of 2017	Estimated Life	Estimated Time To First Replacement	Number of Annual Phases *	Quantity	Units of Measure	Unit Cost	Consultant Fee Rep	timated acement osts **	Comments/Recommendations
22 Asphalt Pathway, (4' Wide) @ Tract "J"	photo Pendind	25	2007	11	0	14	1	560	Sq. Ft.	\$5	N	\$2,800	This pathway runs east-west along the right elevation of Lot 76 of the Row Homes. Observed Conditions/Recommended Actions: This component appears to be performing as intended. No action required at this time, (per the 2018/2019 RS Update, Lvl 2)
23 Concrete Curbs & Gutters, (No Sidewalk/Pathway Attached)	Photo Pending	50	2007	11	-50	0	50	1,821	Ln. Ft.	\$10	N	\$18,210	Located at Tracts "A" & "D" Observed Conditions/Recommended Actions: Observed a few location where the concrete was breaking down and could require replacement as soon as this year, (2018/2019). For all other locations it has been assumed that the replacement of this component would be addressed an "As Needed" basis and would take place over an extended period o time.
Sub-Section #4: Retaining Walls													
24 Rock Retaining Wall @ SW Langer Dr. & SW Holland Lane	Photo Bending	50	2007	11	0	39	1	425	Sq. Ft.	\$75	Y	\$34,110	Observed Conditions/Recommended Actions: Appears to be in good condition. It is recommended the Association hire a Geotechnical Engineering firm once every five years to assess the condition of this retaining wall.
25 CMU Retaining Walls, (< 1' Tall)	Photo Pendino	30	2007	11	-10	9	15	500	Sq. Ft.	\$15	N	\$7,500	Located in targeted areas throughout the community. Item photo was taken from a wall located in Tract "G" Observed Conditions/Recommended Actions: Appears to be in good condition. It is recommended the Association add a visual reviews of these components to their maintenance plan to ensure they are structurally sound. This service may be offered by the Association's landscaping contractor.
26 CMU Retaining Walls, (< 3' Tall)	Photo Pending	30	2007	11	-10	9	15	500	Sq. Ft.	\$15	N	\$7,500	Located in targeted areas throughout the community. Item photo was taken from a wall located in Tract "A" Observed Conditions/Recommended Actions: Appears to be in good condition. It is recommended the Association add a visual reviews of these components to their maintenance plan to ensure they are structurally sound. This service may be offered by the Association's landscaping contractor.
SHARED COMMON ELEMENTS #4: MISC COMPONENTS													
Sub-Category #1: Tract "R", (Water Quality & Detention Facility)													
27 Chain-link Fence, (6' Tall Approx.)	Photo Reliting	30	2007	11	0	19	1	400	Ln. Ft.	\$17	N	\$6,800	Observed Conditions/Recommended Actions: Appears to be in good condition. No action required at this time, (per the 2018/2019 RS Update, Lvl 2)

^{*} Quantity of years needed or scheduled to complete the renewal process.

^{**} Renewal costs listed are the current values should the scheduled replacement take place the year this RS was completed...

Arbor Terrace Community - All Lots

Table 3: Shared Common Elements List - Replacement Cost Estimates Are Ba	Component Caption	Estimated Life Expectancy	Assumed Year of Acquisition	Present Age as of 2017	Estimated Life	Estimated Time To First Replacement	Number of	Quantity	Units of Measure	Unit Cost	Add 3rd Party Consultant Fee (Y/N)	Current Estimated Replacement Costs **	Comments/Recommendations
28 CMU Retaining Wall, (2' x 3' Blocks, Stacked Approx. 5' Tall)	Photo Parkling	50	2007	11	0	39	1	750	Sq. Ft.	\$75	Y	\$60,190	Observed Conditions/Recommended Actions: Appears to be in good condition. It is recommended the Association hire a Geotechnical Engineering firm once every five years to assess the condition of this retaining wall.
29 Concrete Flatwork, (Includes Stairs)	PhotoPendires	40	2007	11	0	29	1	240	Sq. Ft.	\$25	Υ	\$6,420	Observed Conditions/Recommended Actions: No visible cracks or sig of failure to the concrete slab were observed. No action at this time, (the 2018/2019 RS update, Lvl 2)
30 Handrails, (Metal)	Photo Pending	30	2007	11	0	19	1	18	Ln. Ft.	\$50	N	\$900	Observed Conditions/Recommended Actions: Appears to be in good condition. No action required at this time, (per the 2018/2019 RS Update, Lvl 2)
Sub-Section #2: Landscaping													
31 Community Landscaping Improvement Project, (Major Renewal Task)	Photo Parding	15	2019	-1	0	16	1	1	EA	\$135,000	Y	\$144,450	Observed Conditions/Recommended Actions: N/A Note: As instructed by the Association, an allowance has been created to fund large updates to the community's landscaping scheme.
Sub-Section#3: Other Misc. Components													
32 Mailbox Kiosks	Photo Pending	25	2007	11	-5	9	10	14	EA	\$1,500	N	\$21,000	Observed Conditions/Recommended Actions: Appears to be in good condition. No action required at this time, (per the 2018/2019 RS Update, Lvl 2) Note: Based on information provided by the local Post Office, the renewal cost for these components are the responsibility of the HOA. Adjustment to the estimated life expectancy was factored to help the Association be proactive should these components require replaceme before their estimated renewal date.

^{*} Quantity of years needed or scheduled to complete the renewal process.

^{**} Renewal costs listed are the current values should the scheduled replacement take place the year this RS was completed..

Arbor Terrace Community - All Lots

Item#	ts List - Replacement Cost Estimates Are Based On Item Description	Component Caption	Estimated Life	Assumed Year of Acquisition	Present Age	Estimated Life	Estimated Time To First Replacement	Number of	Quantity	Units of Measure	Unit Cost	Add 3rd Party Consultant Fee (Y/N)	Current Estimated Replacement	Comments/Recommendations
SHARED COMMON ELEMENTS #5: PROFE	ESSIONAL SERVICES & CONSULTING		Expectancy	Acquisition		Expectancy	Керіасетіеті					(1/N)	Costs **	
Sub-Category #1: Consulting Services														
33 Reserve Study Updates, (Level 2)		MB	5	2018	0	-1	4	1	1	EA	\$4,500	N	\$4,500	Conducted once every three to five years. Scope includes physical observation of the current study's list of components in order to assess their estimated service life require adjustments. Other tasks include client meetings and component list additions.
34 Reserve Study Updates, (Level 3)		Mb	1	2018	0	-1	0	1	1	EA	\$1,500	N	\$1,500	A Level 3 RS accounts for minor adjustments to the funding plan. Because a Level 3 RS does not include site observations or face-to-fac client meetings, information for this update is conducted over the phone and via email communication. Pertinent information such as expenditures made, potential market or industry adjustments that may impact replacement costs to the list of components, and variations to the established funding plan as per the previously completed RS will be gathered during this interview. Per Oregon State Statute a Level 3 RS to be conducted annually.
35 Maintenance Plan		ME	5	2007	11	0	0	1	0	EA	\$4,000	N	\$0	To be discussed with the BOD. No funds are currently allocated for th line item.
Sub-Category #2: Misc Fees														
36 Emergency Renewal Fund		ME	30	2007	11	-30	0	30	1	EA	\$160,000	N	\$160,000	Budgetary Line Item - Covers potential renewal of unknown or unexpected fees or costs. It is recommended that the Association budget \$1,000 per unit, paid over 30 years for any unexpected renewal costs.

^{*} Quantity of years needed or scheduled to complete the renewal process.

^{**} Renewal costs listed are the current values should the scheduled replacement take place the year this RS was completed...

APPENDIX B APPROVED FUNDING PLAN – ALL LOTS TABLE 4: DETAILED CASH FLOW

The "Detailed Cash-Flow" table is generated based on the estimated values established by "Table 3: Shared Common Elements List", (See Appendix A) and is designed to anticipate the necessary cash flow for each year over the 30-year period of this study. The estimated renewal costs listed within Table 4 includes the assumed rate of inflation, (2%) for each of the years leading up to the date of replacement.

Current Vessels	. Cambrilla ti	20.000		Mandhly Car	atribution (Don I	lait !! A a ua u a !! F	V O\- 6	45.00								
	/ Contribution: \$				-	Jnit "Average" F			****	****	****		****	****	****	
	Starting Balance	\$171,327	\$186,439	\$201,391	\$216,176	\$227,052	\$238,176	\$258,128	\$277,935	\$297,591	\$316,203	\$308,591	\$328,811	\$348,777	\$352,546	\$367,259
Total Expenses inflated	•	\$15,468	\$15,777	\$16,093	\$20,129	\$19,990	\$17,078	\$17,419	\$17,768	\$19,002	\$45,280	\$22,695	\$23,149	\$39,465	\$28,612	\$116,085
	at 1% annually	\$1,780	\$1,930	\$2,077	\$2,205	\$2,315	\$2,469	\$2,667	\$2,863	\$3,054	\$3,108	\$3,171	\$3,371	\$3,489	\$3,581	\$3,291
	ve Contribution	\$28,800	\$28,800	\$28,800	\$28,800	\$28,800	\$34,560	\$34,560	\$34,560	\$34,560	\$34,560	\$39,744	\$39,744	\$39,744	\$39,744	\$39,744
	ner Contribution															
F	Ending Balance	\$186,439	\$201,391	\$216,176	\$227,052	\$238,176	\$258,128	\$277,935	\$297,591	\$316,203	\$308,591	\$328,811	\$348,777	\$352,546	\$367,259	\$294,209
	Fiscal Year	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
	Calendar Year	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
SHARED COMMON ELEMENTS #1: TRACT "D", (PARK AREA ADJACENT TO SW BALER	R WAY)															
Sub-Category #1: Tot-Lot																
01 42" Metal Fencing & Gates @ Front Elev Refinishing, (Maintenance Task)																
02 42" Metal Fencing & Gates @ Front Elev Replacement, (Renewal Task)														\$15,853		
03 Concrete Pathways		\$296	\$302	\$308	\$314	\$320	\$327	\$333	\$340	\$347	\$354	\$361	\$368	\$375	\$383	\$391
04 Park Benches											\$4,780					
05 Play Equipment																
Sub-Category #2: Gazebo																
06 Concrete Pathways											\$60	\$61	\$62	\$63	\$65	\$66
07 Concrete Slab/Foundation																
08 Stone Column Bases											\$12,274					
09 Structure																
10 T&G Soffit, (Ventilated)																
11 Park Benches, (Attached)											\$2,390					
12 HOA Bulletin Board, (Free Standing)										\$879						
13 Roofing, (Asphaltic Roof Shingles)																\$6,597
14 Refinishing, (Painting & Staining)					\$3,714										\$4,528	
Sub-Category #3: Misc. Components																
15 Vinyl Fence, (42" Tall)																\$18,407
16 Concrete Pathways		\$360	\$367	\$375	\$382	\$390	\$397	\$405	\$414	\$422	\$430	\$439	\$448	\$457	\$466	\$475
SHARED COMMON ELEMENTS #2: FENCING																
Sub-Category #1: Wood Fencing																
17 6' Cedar Fence, (Good Neighbor Style)																
Sub-Category #2: Vinyl Fencing																
18 Vinyl Fence, (42" Tall)																\$58,862
SHARED COMMON ELEMENTS #3: CONCRETE PATHWAYS & RETAINING WALLS																
Sub-Section #1: Concrete Sidewalks, (5' Wide, w/Attached Curb & Gutter)	_		_	_	_	_	_	_	_	_		_	_		_	
19 SW Holland Lane		\$3,768	\$3,843	\$3,920	\$3,999	\$4,079	\$4,160	\$4,243	\$4,328	\$4,415	\$4,503	\$4,593	\$4,685	\$4,779	\$4,874	\$4,972
Sub-Section #2: Concrete Sidewalks, (5' Wide, w/Detached Curb & Gutter)		/	, , , , , , ,	, -,	,	, ,	. ,	, ,	. ,===	. ,	. ,	. ,	, ,	. ,	. ,	, 2
20 SW Harvester Lane		\$3,686	\$3,760	\$3,835	\$3,912	\$3,990	\$4,070	\$4,151	\$4,235	\$4,319	\$4,406	\$4,494	\$4,584	\$4,675	\$4,769	\$4,864
I		Ψ5,000	Ψ0,100	ψ0,000	Ψ5,0 IL	ψ0,000	Ψ.,σ.σ	Ψ., ισι	Ψ.,200	Ψ.,σισ	ψ.,-100	ψ.,	Ψ.,001	ψ.,σ.σ	ψ.,,,ου	Ψ1,004

	Current Yearly Contribution: \$2	28,800		Monthly Cor	ntribution, (Per U	Init "Average" F	or Year One): \$1	5.00								
	Starting Balance	\$171,327	\$186,439	\$201,391	\$216,176	\$227,052	\$238,176	\$258,128	\$277,935	\$297,591	\$316,203	\$308,591	\$328,811	\$348,777	\$352,546	\$367,259
	Total Expenses inflated at 2% annually	\$15,468	\$15,777	\$16,093	\$20,129	\$19,990	\$17,078	\$17,419	\$17,768	\$19,002	\$45,280	\$22,695	\$23,149	\$39,465	\$28,612	\$116,085
	Interest at 1% annually	\$1,780	\$1,930	\$2,077	\$2,205	\$2,315	\$2,469	\$2,667	\$2,863	\$3,054	\$3,108	\$3,171	\$3,371	\$3,489	\$3,581	\$3,291
	Annual Reserve Contribution	\$28,800	\$28,800	\$28,800	\$28,800	\$28,800	\$34,560	\$34,560	\$34,560	\$34,560	\$34,560	\$39,744	\$39,744	\$39,744	\$39,744	\$39,744
	Other Contribution															
	Ending Balance	\$186,439	\$201,391	\$216,176	\$227,052	\$238,176	\$258,128	\$277,935	\$297,591	\$316,203	\$308,591	\$328,811	\$348,777	\$352,546	\$367,259	\$294,209
	Fiscal Year	1	2	3	4	5	6	7	8	9	10	11	12	13	14	1
	Calendar Year	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	203
Sub-Section #3: Misc. Concrete & Asphalt Pathways																
21 Concrete Pathways, (4' Wide, No Curb or Gutter)		\$160	\$163	\$166	\$170	\$173	\$177	\$180	\$184	\$187	\$191	\$195	\$199	\$203	\$207	\$21
22 Asphalt Pathway, (4' Wide) @ Tract "J"																\$3,69
23 Concrete Curbs & Gutters, (No Sidewalk/Pathway Attached)		\$364	\$371	\$379	\$386	\$394	\$402	\$410	\$418	\$427	\$435	\$444	\$453	\$462	\$471	\$48
Sub-Section #4: Retaining Walls																
24 Rock Retaining Wall @ SW Langer Dr. & SW Holland Lane																
25 CMU Retaining Walls, (< 1' Tall)											\$598	\$609	\$622	\$634	\$647	\$660
26 CMU Retaining Walls, (< 3' Tall)											\$598	\$609	\$622	\$634	\$647	\$660
SHARED COMMON ELEMENTS #4: MISC COMPONENTS																
Sub-Category #1: Tract "R", (Water Quality & Detention Facility)																
27 Chain-link Fence, (6' Tall Approx.)																
28 CMU Retaining Wall, (2' x 3' Blocks, Stacked Approx. 5' Tall)																
29 Concrete Flatwork, (Includes Stairs)																
30 Handrails, (Metal)																
Sub-Section #2: Landscaping																
31 Community Landscaping Improvement Project, (Major Renewal Task)																
Sub-Section#3: Other Misc. Components																
32 Mailbox Kiosks											\$2,510	\$2,560	\$2,611	\$2,663	\$2,717	\$2,77
SHARED COMMON ELEMENTS #5: PROFESSIONAL SERVICES &	CONSULTING															
Sub-Category #1: Consulting Services																
33 Reserve Study Updates, (Level 2)						\$4,871					\$5,378					\$5,93
34 Reserve Study Updates, (Level 3)		\$1,500	\$1,530	\$1,561	\$1,592		\$1,656	\$1,689	\$1,723	\$1,757		\$1,828	\$1,865	\$1,902	\$1,940	
35 Maintenance Plan																
Sub-Category #2: Misc Fees																
36 Emergency Renewal Fund		\$5,333	\$5,440	\$5,549	\$5,660	\$5,773	\$5,888	\$6,006	\$6,126	\$6,249	\$6,374	\$6,501	\$6,631	\$6,764	\$6,899	\$7,037

Current Vendu Co		20.000		Manthly Car	atribution (Dayl	Init !! A	V O\- ¢4	F 00								
Current Yearly Co			*********			Jnit "Average" Fo			400.405	*	0.400.470	A 450.000	*	4000 507	4050.070	
	ing Balance	\$294,209	\$317,902	\$142,039	\$163,193	\$184,036	\$23,589	\$51,982	\$80,165	\$105,206	\$126,170	\$150,322	\$186,987	\$223,507	\$259,870	\$296,064
Total Expenses inflated at 2	-	\$25,057	\$223,857	\$26,070	\$26,591	\$207,185	\$24,545	\$25,036	\$28,443	\$32,749	\$29,785	\$25,459	\$25,968	\$26,487	\$27,017	\$54,852
	1% annually	\$3,045	\$2,288	\$1,519	\$1,728	\$1,033	\$376	\$657	\$922	\$1,151	\$1,376	\$1,678	\$2,042	\$2,405	\$2,766	\$2,989
Annual Reserve 0		\$45,706	\$45,706	\$45,706	\$45,706	\$45,706	\$52,561	\$52,561	\$52,561	\$52,561	\$52,561	\$60,446	\$60,446	\$60,446	\$60,446	\$60,446
	Contribution															
Endi	ing Balance	\$317,902	\$142,039	\$163,193	\$184,036	\$23,589	\$51,982	\$80,165	\$105,206	\$126,170	\$150,322	\$186,987	\$223,507	\$259,870	\$296,064	\$304,646
	Fiscal Year	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
Ca	lendar Year	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	204
SHARED COMMON ELEMENTS #1: TRACT "D", (PARK AREA ADJACENT TO SW BALER W	AY)															
Sub-Category #1: Tot-Lot																
01 42" Metal Fencing & Gates @ Front Elev Refinishing, (Maintenance Task)									\$2,906							
02 42" Metal Fencing & Gates @ Front Elev Replacement, (Renewal Task)																
03 Concrete Pathways		\$398	\$406	\$414	\$423	\$431	\$440	\$449	\$458	\$467	\$476	\$486	\$495	\$505	\$515	\$52
04 Park Benches																\$7,10
05 Play Equipment						\$43,704										
Sub-Category #2: Gazebo																
06 Concrete Pathways		\$67	\$69	\$70	\$71	\$73	\$74	\$76	\$77	\$79	\$80	\$82	\$84	\$85	\$87	
07 Concrete Slab/Foundation																
08 Stone Column Bases																
09 Structure						\$109,261										
10 T&G Soffit, (Ventilated)						\$14,568										
11 Park Benches, (Attached)																\$3,55
12 HOA Bulletin Board, (Free Standing)										\$1,183						
13 Roofing, (Asphaltic Roof Shingles)																
14 Refinishing, (Painting & Staining)										\$5,519						
Sub-Category #3: Misc. Components																
15 Vinyl Fence, (42" Tall)																
16 Concrete Pathways		\$485	\$494	\$504	\$514	\$524	\$535	\$546	\$557	\$568	\$579	\$591	\$602	\$614	\$627	\$63
SHARED COMMON ELEMENTS #2: FENCING																
Sub-Category #1: Wood Fencing																
17 6' Cedar Fence, (Good Neighbor Style)																
Sub-Category #2: Vinyl Fencing																
18 Vinyl Fence, (42" Tall)																
SHARED COMMON ELEMENTS #3: CONCRETE PATHWAYS & RETAINING WALLS																
Sub-Section #1: Concrete Sidewalks, (5' Wide, w/Attached Curb & Gutter)																
19 SW Holland Lane		\$5,071	\$5,173	\$5,276	\$5,382	\$5,489	\$5,599	\$5,711	\$5,825	\$5,942	\$6,061	\$6,182	\$6,305	\$6,432	\$6,560	#6.60
		φ3,071	φο, ι τ ο	φ5,276	φυ,302	φυ,409	φ0,099	φ5,/11	φ5,025	φ0,942	φο,υο Ι	φ0,102	φυ,ουσ	φ0,432	φ0,500	\$6,69
Sub-Section #2: Concrete Sidewalks, (5' Wide, w/Detached Curb & Gutter)		#4.004	#5.004	#5.400	# 5 005	# F 070	ФE 470	# 5 507	#5.000	Ø5 046	# 5.000	00.040	60.400	#0.000	#0.440	00.51
20 SW Harvester Lane		\$4,961	\$5,061	\$5,162	\$5,265	\$5,370	\$5,478	\$5,587	\$5,699	\$5,813	\$5,929	\$6,048	\$6,169	\$6,292	\$6,418	\$6,546

36 Emergency Renewal Fund

Table 4: Detailed Cash Flow																
	Current Yearly Contribution: \$2	28,800		Monthly Co	ntribution, (Per l	Jnit "Average" F	or Year One): \$1	5.00								
	Starting Balance	\$294,209	\$317,902	\$142,039	\$163,193	\$184,036	\$23,589	\$51,982	\$80,165	\$105,206	\$126,170	\$150,322	\$186,987	\$223,507	\$259,870	\$296,064
	Total Expenses inflated at 2% annually	\$25,057	\$223,857	\$26,070	\$26,591	\$207,185	\$24,545	\$25,036	\$28,443	\$32,749	\$29,785	\$25,459	\$25,968	\$26,487	\$27,017	\$54,852
	Interest at 1% annually	\$3,045	\$2,288	\$1,519	\$1,728	\$1,033	\$376	\$657	\$922	\$1,151	\$1,376	\$1,678	\$2,042	\$2,405	\$2,766	\$2,989
	Annual Reserve Contribution	\$45,706	\$45,706	\$45,706	\$45,706	\$45,706	\$52,561	\$52,561	\$52,561	\$52,561	\$52,561	\$60,446	\$60,446	\$60,446	\$60,446	\$60,446
	Other Contribution															
	Ending Balance	\$317,902	\$142,039	\$163,193	\$184,036	\$23,589	\$51,982	\$80,165	\$105,206	\$126,170	\$150,322	\$186,987	\$223,507	\$259,870	\$296,064	\$304,646
	Fiscal Year	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
	Calendar Year	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047
ub-Section #3: Misc. Concrete & Asphalt Pathways																
21 Concrete Pathways, (4' Wide, No Curb or Gutter)		\$215	\$220	\$224	\$229	\$233	\$238	\$243	\$247	\$252	\$257	\$262	\$268	\$273	\$279	\$284
22 Asphalt Pathway, (4' Wide) @ Tract "J"																
23 Concrete Curbs & Gutters, (No Sidewalk/Pathway Attached)		\$490	\$500	\$510	\$520	\$531	\$541	\$552	\$563	\$574	\$586	\$598	\$609	\$622	\$634	\$647
ub-Section #4: Retaining Walls																
24 Rock Retaining Wall @ SW Langer Dr. & SW Holland Lane																
25 CMU Retaining Walls, (< 1' Tall)		\$673	\$686	\$700	\$714	\$728	\$743	\$758	\$773	\$788						
26 CMU Retaining Walls, (< 3' Tall)		\$673	\$686	\$700	\$714	\$728	\$743	\$758	\$773	\$788						ļ
HARED COMMON ELEMENTS #4: MISC COMPONENTS																
ub-Category #1: Tract "R", (Water Quality & Detention Facility)																
27 Chain-link Fence, (6' Tall Approx.)						\$9,906										
28 CMU Retaining Wall, (2' x 3' Blocks, Stacked Approx. 5' Tall)																
29 Concrete Flatwork, (Includes Stairs)																\$11,401
30 Handrails, (Metal)						\$1,311										
ub-Section #2: Landscaping																
31 Community Landscaping Improvement Project, (Major Renewal Task)			\$198,299													
ub-Section#3: Other Misc. Components																
32 Mailbox Kiosks		\$2,826	\$2,883	\$2,941	\$2,999											
HARED COMMON ELEMENTS #5: PROFESSIONAL SERVICES & (CONSULTING															
ub-Category #1: Consulting Services																
33 Reserve Study Updates, (Level 2)						\$6,556					\$7,238					\$7,991
34 Reserve Study Updates, (Level 3)		\$2,019	\$2,059	\$2,100	\$2,142		\$2,229	\$2,273	\$2,319	\$2,365		\$2,461	\$2,510	\$2,560	\$2,612	
35 Maintenance Plan																
ub-Category #2: Misc Fees																

\$7,178

\$7,322

\$7,468

\$7,617

\$7,770

\$7,925

\$8,084

\$8,245

\$8,410

\$8,578

\$8,750

\$8,925

\$9,103

\$9,285

\$9,471

APPENDIX C FIVE YEAR EXPENDITURE OUTLOOK – ALL LOTS

	2018 / 2019	
03	Concrete Pathways @ Tract "B"	\$296
16	Concrete Pathways	\$360
19	SW Holland Lane	\$3,768
20	SW Harvester Lane	\$3,686
21	Concrete Pathways, (4' Wide, No Curb or Gutter)	\$160
23	Concrete Curbs & Gutters, (No Sidewalk/Pathway Attached)	\$364
34	Reserve Study Updates, (Level 3)	\$1,500
36	Emergency Renewal Fund	\$5,333
		\$15,468

	2019 / 2020									
03	Concrete Pathways @ Tract "B"	\$302								
16	Concrete Pathways	\$367								
19	SW Holland Lane	\$3,843								
20	SW Harvester Lane	\$3,760								
21	Concrete Pathways, (4' Wide, No Curb or Gutter)	\$163								
23	Concrete Curbs & Gutters, (No Sidewalk/Pathway Attached)	\$371								
34	Reserve Study Updates, (Level 3)	\$1,530								
36	Emergency Renewal Fund	\$5,440								
		\$15,777								

	2020 / 2021								
03	Concrete Pathways @ Tract "B"	\$308							
16	Concrete Pathways	\$375							
19	SW Holland Lane	\$3,920							
20	SW Harvester Lane	\$3,835							
21	Concrete Pathways, (4' Wide, No Curb or Gutter)	\$166							
23	Concrete Curbs & Gutters, (No Sidewalk/Pathway Attached)	\$379							
34	Reserve Study Updates, (Level 3)	\$1,561							
36	Emergency Renewal Fund	\$5,549							
		\$16,093							

	2021 / 2022	
03	Concrete Pathways @ Tract "B"	\$314
14	Refinishing, (Painting & Staining)	\$3,714
16	Concrete Pathways	\$382
19	SW Holland Lane	\$3,999
20	SW Harvester Lane	\$3,912
21	Concrete Pathways, (4' Wide, No Curb or Gutter)	\$170
23	Concrete Curbs & Gutters, (No Sidewalk/Pathway Attached)	\$386
34	Reserve Study Updates, (Level 3)	\$1,592
36	Emergency Renewal Fund	\$5,660
		\$20,129

2022 / 2023								
03	Concrete Pathways @ Tract "B"	\$320						
16	Concrete Pathways	\$390						
19	SW Holland Lane	\$4,079						
20	SW Harvester Lane	\$3,990						
21	Concrete Pathways, (4' Wide, No Curb or Gutter)	\$173						
23	Concrete Curbs & Gutters, (No Sidewalk/Pathway Attached)	\$394						
33	Reserve Study Updates, (Level 2)	\$4,871						
36	Emergency Renewal Fund	\$5,773						
		\$19,990						

5. FUNDING ALTERNATIVES - ROWHOMES

Summary of Data & Results

Property Name	Arbor Terrace Co	ommunity - Rowhomes
Entity Name		Arbor Terrace HOA
Current Date		June 14, 2018
Year Built, (Conversion Year)		2007
Starting Year, (Forecasted Fiscal Year)		2018
Dollar Year, (Current Fiscal Year)		2018
Fiscal Year Start Date		July 1, 2018
Fiscal Year End Date		June 30, 2019
Assumed Inflation Rate		2.00%
Earned Interest Rate		1.00%
Estimated Starting Balance		\$191,000
Number of Units		65
Scenario 1 (Optional Funding Path)		
Current Yearly Contribution:	\$	63,960
Monthly Contribution, (Per Unit "Average" For Year One):	\$	82
Lowest Annual Closing Balance	\$	17,946
Largest Annual Closing Balance	\$ \$ \$	2,067,659
30-Year Closing Balance	\$	2,067,659
Scenario 2 (Optional Funding Path)		
Optional Yearly Contribution, (Year One):	\$	63,960
Monthly Contribution, (Per Unit "Average" For Year One):	\$	82
Lowest Annual Closing Balance		19,683
Largest Annual Closing Balance	\$ \$ \$	1,014,050
30-Year Closing Balance	\$	1,014,050
Consulting Allowance		7%

Page 29 of 74

Arbor Terrace Community - Rowhomes - Funding Graph #1 - FINAL


Percentage of Anticipated Expenditures By Groups (Groups are formed by multiple factors such as similar renewal timelines & common functions)

□ Building Envelope Components "NOT" Replaced in 2013 \$688,817

■ Building Envelope Components Replaced in 2013 \$1,295,363

■ Fencing & Asphalt Roadways \$202,412

■Misc & Professional Services \$89,961



Optional Funding Path's 30 Year Ending Balance: Scenario 1: Optional Funding Path's 30 Year Ending Balance: \$1,014,050 \$2,067,659 Scenario 2: SAO? A OC ⁻²62 0402 Annual Ending Balance - Scenario Comparison 8507 8507 *CO2 203 0502 80/2 9₀0 *¿02 502 0202 8/05 Scenario 2 \$0 \$2,500,000 \$2,000,000 \$1,500,000 \$1,000,000 \$500,000 Yearly Ending Balance for Each Scenario

Arbor Terrace Community - Rowhomes - Funding Graph #2 - FINAL

Rowhomes - Optional Funding Plan, (Scenario One)

This scenario is based on the funding plan designed and agreed upon by the Association's Board of Directors in 2018, (2018/2019 Fiscal Year). The starting account balance within the reserves at year one will be \$191,00 with an annual contribution of \$63,960, (figures were provided by Ms. Amy Boyle). All rate increases to the reserve's annual contributions have also been established by the Association's BOD.

Analysis

The amount of funds within the reserve's account will maintain a positive balance over the next 30 years, (July 1, 2018 through June 30, 2048). This is contingent on the Association following the funding plan and the scheduled annual increases to the contributions that they have established within this RS over this same period of time. This will also be impacted on how well they maintain and care for their shared common elements.

The chart below shows the three largest renewal periods over the 30-year scope set by this study:

<u>Periods</u>	Major Renewal Task	Est. Cost
2023 – 2025	Exterior Painting Renewal Cycle #1 & Roof Replacement	\$775K
2031	Cedar Fence Renewal	\$80K
2043 – 2046	Exterior Painting Renewal Cycle #3 & Cedar Fence Renewal	\$365K

Please note, that the forecasted repairs and replacements do not represent a fixed schedule for any given element or component reviewed. Such repairs or replacements may be required sooner or later than we have anticipated. It should also be noted that these repairs and replacements may not all take place within one year's time and may not be required at all. However, it is prudent to budget for such repairs since failure of some components is somewhat unpredictable.

Results

This funding plan as approved by the Association will maintain an amount greater than \$0, (Baseline Funding) over the 30-year term set by this RS. MH can recommend this funding plan because it provides the necessary amount of available funds to cover all of the Association's future anticipated replacement needs in terms of their shared common elements.

Annual contributions within this funding plan have been aligned with the list of shared common elements shown in Appendix D, Table 3, (assuming the expenditure is scheduled to be replaced by June 30, 2048). The ensuing two documents, (Table 1 & Table 2) illustrate what the Association should anticipate over the next 30 years should they follow this funding path. For a detailed breakout of the anticipated cash flow for this funding plan see Appendix E, Table 4.

Arbor Terrace Community - Rowhomes Scenario 1 - Optional Funding Path <u>Table 1: Cash Flow Summary</u>

Current Yearly Contribution:

Monthly Contribution, (Per Unit "Average" For Year One):

Assumed Interest Rate
Assumed Inflation Rate
Reserve's Starting Balance as of July 1, 2018
Reserve's Minimum Annual Ending Balance Within 30 Year Scope


\$63,960
\$82

\$82

Assumed Inflation Rate
2.00%
Reserve's Minimum Annual Ending Balance Within 30 Year Scope
\$11,900

#	Year	Annual Opening Balance	Annual Contribution	Annual Rate Increase	Other Contributions	Estimated Annual Expenditures	Projected Earned Interest	Annual Closing Balance
1	2018/2019	\$191,000	\$63,960	20.7%	\$0	\$33,447	\$2,063	\$223,576
2	2019/2020	\$223,576	\$73,554	15.0%	\$14,400	\$44,316	\$2,382	\$269,596
3	2020/2021	\$269,596	\$84,587	15.0%	\$14,400	\$34,798	\$2,945	\$336,730
4	2021/2022	\$336,730	\$97,275	15.0%	\$14,400	\$38,121	\$3,663	\$413,948
5	2022/2023	\$413,948	\$107,003	10.0%	\$14,400	\$41,329	\$4,468	\$498,489
6	2023/2024	\$498,489	\$117,703	10.0%	\$14,400	\$291,122	\$4,118	\$343,588
7	2024/2025	\$343,588	\$123,588	5.0%	\$14,400	\$296,945	\$2,569	\$187,200
8	2025/2026	\$187,200	\$129,768	5.0%	\$14,400	\$314,371	\$949	\$17,946
9	2026/2027	\$17,946	\$129,768	0.0%	\$14,400	\$40,635	\$625	\$122,103
10	2027/2028	\$122,103	\$129,768	0.0%	\$14,400	\$41,448	\$1,663	\$226,485
11	2028/2029	\$226,485	\$129,768	0.0%	\$14,400	\$46,543	\$2,681	\$326,790
12	2029/2030	\$326,790	\$129,768	0.0%	\$0	\$43,123	\$3,701	\$417,136
13	2030/2031	\$417,136	\$129,768	0.0%	\$0	\$43,985	\$4,600	\$507,519
14	2031/2032	\$507,519	\$129,768	0.0%	\$0	\$137,047	\$5,039	\$505,278
15	2032/2033	\$505,278	\$129,768	0.0%	\$0	\$45,762	\$5,473	\$594,757
16	2033/2034	\$594,757	\$129,768	0.0%	\$0	\$71,648	\$6,238	\$659,115
17	2034/2035	\$659,115	\$129,768	0.0%	\$0	\$77,885	\$6,851	\$717,847
18	2035/2036	\$717,847	\$129,768	0.0%	\$0	\$74,542	\$7,455	\$780,527
19	2036/2037	\$780,527	\$129,768	0.0%	\$0	\$1,764	\$8,445	\$916,976
20	2037/2038	\$916,976	\$129,768	0.0%	\$0	\$31,766	\$9,660	\$1,024,637
21	2038/2039	\$1,024,637	\$129,768	0.0%	\$0	\$1,835	\$10,886	\$1,163,455
22	2039/2040	\$1,163,455	\$129,768	0.0%	\$0	\$1,872	\$12,274	\$1,303,625
23	2040/2041	\$1,303,625	\$129,768	0.0%	\$0	\$7,321	\$13,648	\$1,439,720
24	2041/2042	\$1,439,720	\$129,768	0.0%	\$0	\$1,948	\$15,036	\$1,582,576
25	2042/2043	\$1,582,576	\$129,768	0.0%	\$0	\$1,987	\$16,465	\$1,726,822
26	2043/2044	\$1,726,822	\$129,768	0.0%	\$0	\$103,744	\$17,398	\$1,770,243
27	2044/2045	\$1,770,243	\$129,768	0.0%	\$0	\$89,085	\$17,906	\$1,828,832
28	2045/2046	\$1,828,832	\$129,768	0.0%	\$0	\$90,866	\$18,483	\$1,886,216
29	2046/2047	\$1,886,216	\$129,768	0.0%	\$0	\$112,740	\$18,947	\$1,922,190
30	2047/2048	\$1,922,190	\$129,768	0.0%	\$0	\$4,149	\$19,850	\$2,067,659
						\$2,166,144		

Arbor Terrace Community - Rowhomes Scenario 1 - Optional Funding Path <u>Table 2: Cash Flow Chart</u>



APPENDIX D

TABLE 3: SHARED COMMON ELEMENTS LIST, (SCENARIO 1) ROWHOMES

This table provides a list of the shared common elements that includes information such as each component's quantities, dates of initial installation or renewal, and estimated unit costs. In addition, this table includes a list of brief comments or recommendations for each corresponding item. MH recommends that close attention be maintained for systems that have an "elevated maintenance" requirement. These components are typically exposed to conditions where they are unlikely to fulfill their usual service life. However it should be noted that in some instances a heightened maintenance plan can maximize the component's serviceable life span. Where a specific material, component or assembly could not be verified during our review, we have assumed the components are suitable for their intended use. Estimated replacement costs are based on current year dollars, (2018).

Arbor Terrace Community - Rowhomes

Scenario One - Table 3: Shared Common Elements List - Replacement Cost E	stimates Are Based On Current Year Do	ollars, (201	8)										
Item # Item Description	Component Caption	Estimated Life Expectancy	Assumed Year of Acquisition	Present Age as of 2017	Estimated Life	Estimated Time To First Replacement	Number of Annual Phases *	Quantity	Units of Measure	Estimated Unit Cost	Add 3rd Party Consultant Fee (Y/N)	Current Estimated Replacement Costs **	Comments/Recommendations
SHARED COMMON ELEMENTS #1: BUILDING ENVELOPE COMPONENTS											'		
Sub-Section #1: Exterior Cladding Assemblies, (Components "NOT" Replaced During The 2013 Rehab Projection	ct)												
01 Exterior Wall Assemblies - Total Renewal Costs - Deduct Downspouts and gutters		30	2007	11	-19	0	15	28,000	Sq. Ft.	\$20	Y	\$501,700	See Items 1A - 1D for clarification of components covered within this renewal task and their scheduled renewal timelines.
1A - Exterior Wall Assemblies_5 Years or Less Renewal Schedule													Base of Wall Components: Replace cladding and weather-resistive barrier assembly at base of wall with new assemblies that protect the sheathing and provide positive drainage. Buildings G, H, & F have the most damage per General Contractor.
													Front Corner Trim Detail: Replace existing white wood trims with fully primed cedar trims. Note: Rear corner trims are being replaced at all buildings. Existing front corner trims are being left in place as part of th current scope of repair.
1B - Exterior Wall Assemblies_6 to 10 Year Renewal Schedule													Column Replacement Work: Replace all cladding, trim, and weather- resistive barrier assemblies on entrance columns of all townhomes with new assemblies that provide positive drainage. Note: Damaged trim is currently being replaced and venting is being provided for existing columns as part of the current scope. However, upper trims are not protected with flashing and cladding/trim is not typically incorporated in the current repair. Replace Exposed Gypsum @ Eaves: Replace exposed gypsum board eaves to correct staining. Note: Eaves can be addressed most economically at same time that roof is replaced.
1C - Exterior Wall Assemblies_11 to 20 Year Renewal Schedule													Exterior Wall Assemblies @ Side & Rear Elevations: Replace all cladding and weather-resistive barrier with new assemblies that will provide positive drainage and improve the building's air barrier. It shot be noted; repairs conducted in 2013 where panel siding exist, these areas have a fully integrated rain-screen system installed. However, from a rain-screen drainage medium from being installed. Scope may include replacing gutters and downspouts that were not replaced 2013. Exterior Wall Assemblies - Misc. Cladding & Trim Details: a) Replace belly band trim on building A with new assemblies that protect that provide positive drainage. b) Replace cladding at front entrance gable with new assemblies that provide positive drainage. c) Replace all cladding on engaged columns between garage doors with new assemblies that provide positive drainage.
Sub-Section #2: Exterior Cladding Assemblies													
02 Exterior Wall Assemblies - Siding & Trim Details, (Replaced in 2013)		50	2013	5	0	45	1	52,000	Sq. Ft.	\$18	N	\$936,000	Observed Conditions/Recommended Actions: Components appear to performing as intended. It is recommended the Association regularly conduct an assessment of each buildings' exterior envelope systems a outlined in Item #14 & #15. Note: These components were replaced during the 2013 "targeted" exterior envelope rehabilitation project.

* Quantity of years needed or scheduled to complete the renewal process.

** Renewal costs listed are the current values should the scheduled replacement take place the year this RS was completed...

Arbor Terrace Community - Rowhomes

Scenario One - Table 3: Shared Common Ele	ements List - Replacement Cost Estimate	s Are Based On Current Year Do Component Caption	Estimated Life	Assumed Year of Acquisition	Present Age as of 2017	Estimated Life	Estimated Time To First Replacement	Number of Annual Phases *	Quantity	Units of Measure	Estimated Unit Cost	Add 3rd Party Consultant Fee (Y/N) Costs	ted Comments/Recommendations
03 Exterior Finishes: Paint & Sealant, (Caulking)		Photo Pantino	10	2013	5	0	5	3	80,000	Sq. Ft.	\$1.95	N \$15	Observed Conditions/Recommended Actions: Components appear to be performing as intended. It is recommended the Association regularly conduct an assessment of each buildings' exterior envelope systems as outlined in Item #14 & #15. Note: Renewal costs covers the replacement of both fill-it joints and dynamic sealant joints.
Sub-Section #3: Roofing Assemblies													
04 Roofing System, (Asphaltic Roof Shingles)			25	2007	11	-9	5	3	72,500	Sq. Ft.	\$5.50	Y \$42	Observed Conditions/Recommended Actions: Components appear to b performing as intended. It is recommended that these components be maintained annually and that regular maintenance tasks are in place to help prolong their estimated life cycle. Note: As part of this years RS update, (2018/2019) MH conducted a limited visual review of roofing assemblies of three buildings. As noted above, we observed no extensive wear or loss of roof granulars that would warrant either a full strip and replacement or a targeted rehab of the roofing assemblies on the Row Homes at this time.
05 Gutters & Downspouts			25	2007	11	-9	5	3	1	EA	\$97,500.00	Y \$10	Observed Conditions/Recommended Actions: These components were replaced in 2013. Some locations were dented or damaged but appeared to be performing as intended. It is recommended the Association add routine maintenance tasks to their maintenance plan to help prolong the life of these components and to ensure they continue t perform as designed.
Sub-Section #4: Misc. Exterior Cladding Assemblies													
06 Lighting: Wall-Mounted Lamp, (Rear Elevation)		Proto Pendins	20	2013	5	-12	3	25	65	EA	\$75	N \$	Observed Conditions/Recommended Actions: Limited quantities observed. Funding plan assumes these components will be replaced o an "As-Needed" basis and will take place over an extended period of time.
07 Electrical Outlet			20	2013	5	-12	3	25	130	EA	\$100	N \$1	Observed Conditions/Recommended Actions: No access to the rear elevations was provided during our field observations. Funding plan assumes these components will be replaced on an "As-Needed" basis and will take place over an extended period of time.
08 Hose Bib			20	2007	11	-6	3	25	130	EA	\$100	N \$1	Observed Conditions/Recommended Actions: Limited quantities observed. Funding plan assumes these components will be replaced o an "As-Needed" basis and will take place over an extended period of time.

^{*} Quantity of years needed or scheduled to complete the renewal process.

^{**} Renewal costs listed are the current values should the scheduled replacement take place the year this RS was completed...

Arbor Terrace Community - Rowhomes

Scenario One - Table 3: Shared Common Elements List - Replacement Cost Estimates Are Based On Current Year Dollars, (2018)

Item # Item Description	Component Caption	Estimated Life	Assumed Year of Acquisition	Present Age as of 2017	Adjustment To Estimated Life Expectancy	To First	Number of	Quantity	Units of Measure	Estimated Unit Cost	Consultant Fee R	Current Estimated eplacement Costs **	Comments/Recommendations
SHARED COMMON ELEMENTS #2: FENCING													
Sub-Category #2: Wood Fencing													
09 6' Cedar Fence, (Good Neighbor Style)		15	2016	2	0	13	1	1,464	Ln. Ft.	\$41	N	\$60,020	Observed Conditions/Recommended Actions: This component was just replaced in 2016 and appear to be in good condition. Note: The Association has instructed that they will no longer be refinishing the wood fencing located throughout the community. However they intend to add a maintenance task for regular scheduled cleaning. Funds required for this task will be drawn from the Operating Budget. Estimated unit costs were provide by the Association's contractor, (Charter Construction).
SHARED COMMON ELEMENTS #3: ASPHALT ROADWAYS													
Sub-Section #1: Asphalt Roadways - Slurry Seal, (Maintenance Task)													
10 Tract A	Photo Pendins	10	2007	11	3	3	1	1,730	Sq. Ft.	\$0.35	N	\$610	Per the Association's direction, the renewal costs for this component will be addressed through the "All Lots" funding plan. Observed Conditions/Recommended Actions: These components were recently replaced and appear to be in good condition. No action required at this time, (per the 2018/2019 RS Update, Lvl 2) Note: Estimated costs also includes restriping and other painted marking on the surfaces the asphalt.
11 Tract D	Photo Perding	10	2007	11	3	3	1	1,794	Sq. Ft.	\$0.35	N	\$630	The Row Homes are responsible for 19% of the renewal costs for this component. The remaining 81% are covered within the Tamarack Homes RS. Observed Conditions/Recommended Actions: These components were recently replaced and appear to be in good condition. No action required at this time, (per the 2018/2019 RS Update, Lvl 2) Note: Estimated costs also includes restriping and other painted marking on the surfaces the asphalt.
Sub-Section #2: Asphalt Roadways - Re-Top Application, (Renewal Task)													
12 Tract A	Photo Pendins	30	2007	11	0	19	1	1,730	Sq. Ft.	\$3.00	N	\$5,190	The Row Homes are responsible for 23% of the renewal costs for this component. The remaining 77% are covered within the Tamarack Homes RS. Observed Conditions/Recommended Actions: Appears to be in good condition. No action required at this time, (per the 2018/2019 RS Update, Lvl 2). Note: Renewal scope includes full demo or grinding of asphalt surface and apply new layers. It is recommended the Association consider hiring a Consultant/Engineer who specialize in this field during the renewal period for this component.
13 Tract D	Photo Pending	30	2007	11	0	19	1	1,794	Sq. Ft.	\$3.00	N	\$5,380	The Row Homes are responsible for 19% of the renewal costs for this component. The remaining 81% are covered within the Tamarack Homes RS. Observed Conditions/Recommended Actions: Appears to be in good condition. No action required at this time, (per the 2018/2019 RS Update, LvI 2). Note: Renewal scope includes full demo or grinding of asphalt surface and apply new layers. It is recommended the Association consider hiring a Consultant/Engineer who specialize in this field during the renewal period for this component.

^{*} Quantity of years needed or scheduled to complete the renewal process.

^{**} Renewal costs listed are the current values should the scheduled replacement take place the year this RS was completed...

Arbor Terrace Community - Rowhomes

Scenario One - Table 3: Shared Common Elements List - Replacement Cost Estimates Are Based On Current Year Dollars, (2018)

Item#	Item Description	Component Caption	Estimated Life Expectancy	Assumed Year of Acquisition	Present Age as of 2017	Adjustment To Estimated Life Expectancy	Estimated Time To First Replacement	Number of Annual Phases *	Quantity	Units of Measure	Estimated Unit Cost	Add 3rd Party Consultant Fee (Y/N)	Current Estimated Replacement Costs **	Comments/Recommendations
	COMMON ELEMENTS #4: PROFESSIONAL SERVICES													
Sub-Ca	tegory #1: Building Envelope Assessments													
14	Building Envelope Condition Assessment - Three Year Review	ME	3	2013	5	4	4	1	1	EA	\$3,500	N	\$3,500	It is recommended the Association schedule once every three years a visual only building envelope assessment of the exterior wall assemblies for the townhomes.
15	Building Envelope Condition Assessment - Six Year Performance Review	41 ^{lb}	6	2013	5	0	1	1	1	EA	\$10,000	N	\$10,000	MH recommends that the Association hire a licensed architectural engineering firm that specialize in the field of exterior cladding systems to conduct comprehensive condition assessment every six years. Scope should include exploratory openings as part of this assessment to see the existing conditions of the underlying wall assembles. Costs provided include contractor fees that will be required to assist with the opening and closing of the areas observed as part of the exploratory opening phase typically included as part of this kind of an assessment.

* Quantity of years needed or scheduled to complete the renewal process.

^{**} Renewal costs listed are the current values should the scheduled replacement take place the year this RS was completed...

APPENDIX E

TABLE 4: DETAILED CASH FLOW, (SCENARIO ONE) ROWHOMES

The "Detailed Cash-Flow" table is generated based on the estimated values established by "Table 3: Shared Common Elements List, (Scenario One)", (See Appendix D) and is designed to anticipate the necessary cash flow for each year over the 30-year period of this study. The estimated renewal costs listed within Table 4 includes the assumed rate of inflation, (2%) for each of the years leading up to the date of replacement.

Current Yearly Contribution: \$6	3,960		Monthly Con	tribution, (Per U	Init "Average" F	or Year One): \$8	32								
Starting Balance	\$191,000	\$223,576	\$269,596	\$336,730	\$413,948	\$498,489	\$343,588	\$187,200	\$17,946	\$122,103	\$226,485	\$326,790	\$417,136	\$507,519	\$505,278
Total Expenses inflated at 2% annually	\$33,447	\$44,316	\$34,798	\$38,121	\$41,329	\$291,122	\$296,945	\$314,371	\$40,635	\$41,448	\$46,543	\$43,123	\$43,985	\$137,047	\$45,762
Interest at 1% annually	\$2,063	\$2,382	\$2,945	\$3,663	\$4,468	\$4,118	\$2,569	\$949	\$625	\$1,663	\$2,681	\$3,701	\$4,600	\$5,039	\$5,473
Annual Reserve Contribution	\$63,960	\$73,554	\$84,587	\$97,275	\$107,003	\$117,703	\$123,588	\$129,768	\$129,768	\$129,768	\$129,768	\$129,768	\$129,768	\$129,768	\$129,768
Other Contributions Via Special Assessment, (Per the direction of the Assocition)		\$14,400	\$14,400	\$14,400	\$14,400	\$14,400	\$14,400	\$14,400	\$14,400	\$14,400	\$14,400				
Ending Balance	\$223,576	\$269,596	\$336,730	\$413,948	\$498,489	\$343,588	\$187,200	\$17,946	\$122,103	\$226,485	\$326,790	\$417,136	\$507,519	\$505,278	\$594,757
Fiscal Year	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
Calendar Year	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
SHARED COMMON ELEMENTS #1: BUILDING ENVELOPE COMPONENTS															
Sub-Section #1: Exterior Cladding Assemblies, (Components "NOT" Replaced During The 2013 Rehab Project)															
01 Exterior Wall Assemblies - Total Renewal Costs - Deduct Downspouts and gutters	\$33,447	\$34,116	\$34,798	\$35,494	\$36,204	\$36,928	\$37,666	\$38,420	\$39,188	\$39,972	\$40,771	\$41,587	\$42,418	\$43,267	\$44,132
Sub-Section #2: Exterior Cladding Assemblies															
02 Exterior Wall Assemblies - Siding & Trim Details, (Replaced in 2013)															
03 Exterior Finishes: Paint & Sealant, (Caulking)						\$57,412	\$58,560	\$59,732							
Sub-Section #3: Roofing Assemblies															
04 Roofing System, (Asphaltic Roof Shingles)						\$157,022	\$160,163	\$163,366							
05 Gutters & Downspouts						\$38,396	\$39,164	\$39,947							
Sub-Section #4: Misc. Exterior Cladding Assemblies															
06 Lighting: Wall-Mounted Lamp, (Rear Elevation)				\$207	\$211	\$216	\$220	\$224	\$229	\$233	\$238	\$243	\$248	\$253	\$258
07 Electrical Outlet				\$552	\$563	\$574	\$586	\$597	\$609	\$621	\$634	\$647	\$659	\$673	\$686
08 Hose Bib				\$552	\$563	\$574	\$586	\$597	\$609	\$621	\$634	\$647	\$659	\$673	\$686
SHARED COMMON ELEMENTS #2: FENCING															
Sub-Category #2: Wood Fencing															
09 6' Cedar Fence, (Good Neighbor Style)														\$77,642	
SHARED COMMON ELEMENTS #3: ASPHALT ROADWAYS															
Sub-Section #1: Asphalt Roadways - Slurry Seal, (Maintenance Task)															
10 Tract A				\$647										\$789	
11 Tract D				\$669										\$815	
Sub-Section #2: Asphalt Roadways - Re-Top Application, (Renewal Task)															
12 Tract A															
13 Tract D															
SHARED COMMON ELEMENTS #4: PROFESSIONAL SERVICES															
Sub-Category #1: Building Envelope Assessments															
14 Building Envelope Condition Assessment - Three Year Review					\$3,789						\$4,266				
15 Building Envelope Condition Assessment - Six Year Performance Review		\$10,200						\$11,487						\$12,936	

Current Yearly Contribution: \$6	Current Yearly Contribution: \$63,960							Monthly Contribution, (Per Unit "Average" For Year One): \$82								
Starting Balance	\$594,757	\$659,115	\$717,847	\$780,527	\$916,976	\$1,024,637	\$1,163,455	\$1,303,625	\$1,439,720	\$1,582,576	\$1,726,822	\$1,770,243	\$1,828,832	\$1,886,216	\$1,922,190	
Total Expenses inflated at 2% annually	\$71,648	\$77,885	\$74,542	\$1,764	\$31,766	\$1,835	\$1,872	\$7,321	\$1,948	\$1,987	\$103,744	\$89,085	\$90,866	\$112,740	\$4,149	
Interest at 1% annually	\$6,238	\$6,851	\$7,455	\$8,445	\$9,660	\$10,886	\$12,274	\$13,648	\$15,036	\$16,465	\$17,398	\$17,906	\$18,483	\$18,947	\$19,850	
Annual Reserve Contribution	\$129,768	\$129,768	\$129,768	\$129,768	\$129,768	\$129,768	\$129,768	\$129,768	\$129,768	\$129,768	\$129,768	\$129,768	\$129,768	\$129,768	\$129,768	
Other Contributions Via Special Assessment, (Per the direction of the Assocition)																
Ending Balance	\$659,115	\$717,847	\$780,527	\$916,976	\$1,024,637	\$1,163,455	\$1,303,625	\$1,439,720	\$1,582,576	\$1,726,822	\$1,770,243	\$1,828,832	\$1,886,216	\$1,922,190	\$2,067,659	
Fiscal Year	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	
Calendar Year	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	
SHARED COMMON ELEMENTS #1: BUILDING ENVELOPE COMPONENTS																
Sub-Section #1: Exterior Cladding Assemblies, (Components "NOT" Replaced During The 2013 Rehab Project)																
01 Exterior Wall Assemblies - Total Renewal Costs - Deduct Downspouts and gutters																
Sub-Section #2: Exterior Cladding Assemblies																
02 Exterior Wall Assemblies - Siding & Trim Details, (Replaced in 2013)																
03 Exterior Finishes: Paint & Sealant, (Caulking)	\$69,985	\$71,385	\$72,813								\$85,312	\$87,018	\$88,758			
Sub-Section #3: Roofing Assemblies																
04 Roofing System, (Asphaltic Roof Shingles)																
05 Gutters & Downspouts																
Sub-Section #4: Misc. Exterior Cladding Assemblies																
06 Lighting: Wall-Mounted Lamp, (Rear Elevation)	\$263	\$268	\$273	\$279	\$284	\$290	\$296	\$302	\$308	\$314	\$320	\$327	\$333	\$340	\$347	
07 Electrical Outlet	\$700	\$714	\$728	\$743	\$758	\$773	\$788	\$804	\$820	\$836	\$853	\$870	\$888	\$905	\$923	
08 Hose Bib	\$700	\$714	\$728	\$743	\$758	\$773	\$788	\$804	\$820	\$836	\$853	\$870	\$888	\$905	\$923	
SHARED COMMON ELEMENTS #2: FENCING																
Sub-Category #2: Wood Fencing																
09 6' Cedar Fence, (Good Neighbor Style)														\$104,496		
SHARED COMMON ELEMENTS #3: ASPHALT ROADWAYS																
Sub-Section #1: Asphalt Roadways - Slurry Seal, (Maintenance Task)																
10 Tract A															\$962	
11 Tract D															\$993	
Sub-Section #2: Asphalt Roadways - Re-Top Application, (Renewal Task)																
12 Tract A					\$7,561											
13 Tract D					\$7,838											
SHARED COMMON ELEMENTS #4: PROFESSIONAL SERVICES																
Sub-Category #1: Building Envelope Assessments																
14 Building Envelope Condition Assessment - Three Year Review		\$4,805						\$5,411						\$6,094		
15 Building Envelope Condition Assessment - Six Year Performance Review					\$14,568						\$16,406					

APPENDIX F FIVE YEAR EXPENDITURE OUTLOOK, (SCENARIO ONE) ROWHOMES

Five Year Outlook Sheet, (Scenario 1)

	2018	
01	Exterior Cladding Assemblies, (Components "NOT" Replaced During The 2013 Rehab Project)	\$33,447
		\$33,447

	2019	
01	Exterior Cladding Assemblies, (Components "NOT" Replaced During The 2013 Rehab Project)	\$34,116
15	Building Envelope Condition Assessment - Six Year Performance Review	\$10,200
		\$44,316

2020									
01	Exterior Cladding Assemblies, (Components "NOT" Replaced During The 2013 Rehab Project)	\$34,798							
•		\$34,798							

	2021	
01	Exterior Cladding Assemblies, (Components "NOT" Replaced During The 2013 Rehab Project)	\$35,494
06	Lighting: Wall-Mounted Lamp, (Rear Elevation)	\$207
07	Electrical Outlet	\$552
08	Hose Bib	\$552
10	Tract A	\$647
11	Tract D	\$669
		\$38,121

	2022									
01	Exterior Cladding Assemblies, (Components "NOT" Replaced During The 2013 Rehab Project)	\$36,204								
06	Lighting: Wall-Mounted Lamp, (Rear Elevation)	\$211								
07	Electrical Outlet	\$563								
08	Hose Bib	\$563								
14	Building Envelope Condition Assessment - Three Year Review	\$3,789								
		\$41,329								

Rowhomes - Optional Funding Plan, (Scenario Two)

This scenario is based on the funding path designed and agreed upon by the Association's Board of Directors in 2018, (2018/2019 Fiscal Year). The primary difference between this scenario and scenario one is when and how long the Association plans to address the exterior cladding assemblies of the buildings that were not replaced during the 2013 rehab project. For this scenario the Association has chosen to start the project in fiscal year 16, (2033/2034) and extend the time line over a three-year period, (ending year: 2035/2036). The starting account balance within the reserves at year one will be \$191,000 with an annual contribution of \$63,960, (figures were provided by Ms. Amy Boyle). All rate increases to the reserve's annual contributions have also been established by the Association's BOD.

Analysis

The amount of funds within the reserve's account will maintain a positive balance over the next 30 years, (July 1, 2018 through June 30, 2048). This is contingent on the Association following the funding plan and the scheduled annual increases to the contributions that they have established within this RS over this same period of time. This will also be impacted on how well they maintain and care for their shared common elements.

The chart below shows the three largest renewal periods over the 30-year scope set by this study:

<u>Periods</u>	Major Renewal Task	Est. Cost
2023 – 2025	Exterior Painting Renewal Cycle #1 & Roof Replacement	\$775K
2033 – 2036	Exterior Envelope Rehab Project	\$900K
2043 – 2046	Exterior Painting Renewal Cycle #3 & Cedar Fence Renewal	\$365K

Please note, that the forecasted repairs and replacements do not represent a fixed schedule for any given element or component reviewed. Such repairs or replacements may be required sooner or later than we have anticipated. It should also be noted that these repairs and replacements may not all take place within one year's time and may not be required at all. However, it is prudent to budget for such repairs since failure of some components is somewhat unpredictable.

Results

This funding plan as approved by the Association will maintain an amount greater than \$0, (Baseline Funding) over the 30-year term set by this RS. MH can recommend this funding plan because it provides the necessary amount of available funds to cover all of the Association's future anticipated replacement needs in terms of their shared common elements.


Annual contributions within this funding plan have been aligned with the list of shared common elements shown in Appendix G, Table 3, (assuming the expenditure is scheduled to be replaced by June 30, 2048). The ensuing two documents, (Table 1 & Table 2) illustrate what the Association should anticipate over the next 30 years should they follow this funding path. For a detailed breakout of the anticipated cash flow for this funding plan see Appendix H, Table 4.

Arbor Terrace Community - Rowhomes Scenario 2 - Optional Funding Path <u>Table 1: Cash Flow Summary</u>

Optional Yearly Contribution, (Year One):\$63,960Monthly Contribution, (Per Unit "Average" For Year One):\$82Assumed Interest Rate1.00%Assumed Inflation Rate2.00%Reserve's Starting Balance as of July 1, 2018\$191,000Reserve's Minimum Annual Ending Balance Within 30 Year Scope\$19,682.60

#	Year	Annual Opening Balance	Annual Contributions	Annual Rate Increase	Other Contributions	Estimated Annual Expenditures	Projected Earned Interest	Annual Closing Balance
1	2018/2019	\$191,000	\$63,960	7.1%	\$0	\$0	\$2,230	\$257,190
2	2019/2020	\$257,190	\$63,960	0.0%	\$14,400	\$10,200	\$2,841	\$328,190
3	2020/2021	\$328,190	\$63,960	0.0%	\$14,400	\$0	\$3,602	\$410,152
4	2021/2022	\$410,152	\$63,960	0.0%	\$14,400	\$2,627	\$4,408	\$490,294
5	2022/2023	\$490,294	\$63,960	0.0%	\$14,400	\$5,126	\$5,197	\$568,725
6	2023/2024	\$568,725	\$76,752	20.0%	\$14,400	\$254,195	\$4,800	\$410,483
7	2024/2025	\$410,483	\$76,752	0.0%	\$14,400	\$259,278	\$3,192	\$245,548
8	2025/2026	\$245,548	\$76,752	0.0%	\$14,400	\$275,951	\$1,459	\$62,209
9	2026/2027	\$62,209	\$76,752	0.0%	\$14,400	\$1,447	\$999	\$152,913
10	2027/2028	\$152,913	\$76,752	0.0%	\$14,400	\$1,476	\$1,906	\$244,494
11	2028/2029	\$244,494	\$88,265	15.0%	\$14,400	\$5,772	\$2,857	\$344,244
12	2029/2030	\$344,244	\$88,265	0.0%	\$0	\$1,536	\$3,876	\$434,849
13	2030/2031	\$434,849	\$88,265	0.0%	\$0	\$1,567	\$4,782	\$526,329
14	2031/2032	\$526,329	\$88,265	0.0%	\$0	\$93,780	\$5,236	\$526,050
15	2032/2033	\$526,050	\$88,265	0.0%	\$0	\$1,630	\$5,694	\$618,378
16	2033/2034	\$618,378	\$101,505	15.0%	\$0	\$296,722	\$5,208	\$428,369
17	2034/2035	\$428,369	\$101,505	0.0%	\$0	\$307,461	\$3,254	\$225,667
18	2035/2036	\$225,667	\$101,505	0.0%	\$0	\$308,709	\$1,221	\$19,683
19	2036/2037	\$19,683	\$101,505	0.0%	\$0	\$1,764	\$696	\$120,118
20	2037/2038	\$120,118	\$101,505	0.0%	\$0	\$31,766	\$1,550	\$191,407
21	2038/2039	\$191,407	\$111,655	10.0%	\$0	\$1,835	\$2,463	\$303,690
22	2039/2040	\$303,690	\$111,655	0.0%	\$0	\$1,872	\$3,586	\$417,058
23	2040/2041	\$417,058	\$111,655	0.0%	\$0	\$7,321	\$4,692	\$526,085
24	2041/2042	\$526,085	\$111,655	0.0%	\$0	\$1,948	\$5,809	\$641,601
25	2042/2043	\$641,601	\$111,655	0.0%	\$0	\$1,987	\$6,964	\$758,234
26	2043/2044	\$758,234	\$122,820	10.0%	\$0	\$103,744	\$7,678	\$784,988
27	2044/2045	\$784,988	\$122,820	0.0%	\$0	\$89,085	\$8,019	\$826,742
28	2045/2046	\$826,742	\$122,820	0.0%	\$0	\$90,866	\$8,427	\$867,124
29	2046/2047	\$867,124	\$122,820	0.0%	\$0	\$112,740	\$8,722	\$885,925
30	2047/2048	\$885,925	\$122,820	0.0%	\$0	\$4,149	\$9,453	\$1,014,050
						\$2,276,553		

Arbor Terrace Community - Rowhomes Scenario 2 - Optional Funding Path <u>Table 2: Cash Flow Chart</u>



APPENDIX G

TABLE 3: SHARED COMMON ELEMENTS LIST, (SCENARIO TWO) ROWHOMES

This table provides a list of the shared common elements that includes information such as each component's quantities, dates of initial installation or renewal, and estimated unit costs. In addition, this table includes a list of brief comments or recommendations for each corresponding item. MH recommends that close attention be maintained for systems that have an "elevated maintenance" requirement. These components are typically exposed to conditions where they are unlikely to fulfill their usual service life. However it should be noted that in some instances a heightened maintenance plan can maximize the component's serviceable life span. Where a specific material, component or assembly could not be verified during our review, we have assumed the components are suitable for their intended use. Estimated replacement costs are based on current year dollars, (2018).

Arbor Terrace Community - Rowhomes

Scenario Two - Table 3: Shared Common Elements List - Replacement Cost Estimates Are Based On Current Year Dollars, (2018)

Scenario Two - Table 3: Shared Common Elements List - Replacement Cost Estimates Are Based On Current Year Dollars, (2018)														
Item#	Item Description	Component Caption	Estimated Life Expectancy	Assumed Year of Acquisition	Present Age as of 2017	Estimated Life		Number of Annual Phases *	Quantity	Units of Measure	Estimated Unit Cost	Add 3rd Party Consultant Fee (Y/N)	Current Estimated Replacement Costs **	Comments/Recommendations
SHARED COMMON	ELEMENTS #1: BUILDING ENVELOPE COMPONENTS													
Sub-Section #1: Ext	erior Cladding Assemblies, (Components "NOT" Replaced During The 2013 Rehab Project)													
01 Exterior Wall	Assemblies - Total Renewal Costs - Deduct Downspouts and gutters		30	2007	11	-4	15	3	28,000	Sq. Ft.	\$20	Y	\$501,700	See Items 1A - 1D for clarification of components covered within this renewal task and their scheduled renewal timelines.
• 1A -	Exterior Wall Assemblies_5 Years or Less Renewal Schedule													Base of Wall Components: Replace cladding and weather-resistive barrier assembly at base of wall with new assemblies that protect the sheathing and provide positive drainage. Buildings G, H, & F have th most damage per General Contractor.
														Front Corner Trim Detail: Replace existing white wood trims with fully primed cedar trims. Note: Rear corner trims are being replaced at a buildings. Existing front corner trims are being left in place as part of current scope of repair.
• 1B -	Exterior Wall Assemblies_6 to 10 Year Renewal Schedule													Column Replacement Work: Replace all cladding, trim, and weather- resistive barrier assemblies on entrance columns of all townhomes w new assemblies that provide positive drainage. Note: Damaged trin currently being replaced and venting is being provided for existing columns as part of the current scope. However, upper trims are not protected with flashing and cladding/trim is not typically incorporated the current repair.
														Replace Exposed Gypsum @ Eaves: Replace exposed gypsum boa eaves to correct staining. Note: Eaves can be addressed most economically at same time that roof is replaced.
• 1C -	Exterior Wall Assemblies_11 to 20 Year Renewal Schedule													Exterior Wall Assemblies @ Side & Rear Elevations: Replace all cladding and weather-resistive barrier with new assemblies that will provide positive drainage and improve the building's air barrier. It sh be noted; repairs conducted in 2013 where panel siding exist, these areas have a fully integrated rain-screen system installed. However, areas where lap siding exists, the repairs conducted here were targe preventing a rain-screen drainage medium from being installed. Scomay include replacing gutters and downspouts that were not replace 2013.
														Exterior Wall Assemblies - Misc. Cladding & Trim Details: a) Replace belly band trim on building A with new assemblies that protect that provide positive drainage. b) Replace cladding at front entrance gal with new assemblies that provide positive drainage. c) Replace all cladding on engaged columns between garage doors with new assemblies that provide positive drainage.
Sub-Section #2: Ext	erior Cladding Assemblies													
02 Exterior Wall	Assemblies - Siding & Trim Details, (Replaced in 2013)		50	2013	5	0	45	1	52,000	Sq. Ft.	\$18	N	\$936,000	Observed Conditions/Recommended Actions: Components appear performing as intended. It is recommended the Association regular conduct an assessment of each buildings' exterior envelope system outlined in Item #14 & #15. Note: These components were replaced during the 2013 "targeted"
														exterior envelope rehabilitation project.

* Quantity of years needed or scheduled to complete the renewal process.

^{**} Renewal costs listed are the current values should the scheduled replacement take place the year this RS was completed...

Arbor Terrace Community - Rowhomes

Scenario Two - Table 3: Shared Common Elements List - Replacement Cost Estimates Are Based On Current Year Dollars, (2018)

Scenario Two - Table 3: Shared Common Elements Lis Item # Item Description	- Replacement Cost Estimates Are Based On Curre	Estimated	Assumed Year of	Present Age as of 2017	Estimated Life		Number of Annual Phases *	Quantity	Units of Measure	Estimated Unit Cost	Add 3rd Party Consultant Fee (Y/N) Currer Estimat Replacer Costs	comments/Recommendations
03 Exterior Finishes: Paint & Sealant, (Caulking)	Proto Pendina	10	2013	5	0	5	3	80,000	Sq. Ft.	\$1.95	N \$156	Observed Conditions/Recommended Actions: Components appear to the performing as intended. It is recommended the Association regularly conduct an assessment of each buildings' exterior envelope systems a outlined in Item #14 & #15. Note: Renewal costs covers the replacement of both fill-it joints and dynamic sealant joints.
Sub-Section #3: Roofing Assemblies												
04 Roofing System, (Asphaltic Roof Shingles)		25	2007	11	-9	5	3	72,500	Sq. Ft.	\$5.50	Y \$426	Observed Conditions/Recommended Actions: Components appear to performing as intended. It is recommended that these components be maintained annually and that regular maintenance tasks are in place to help prolong their estimated life cycle. Note: As part of this years RS update, (2018/2019) MH conducted a limited visual review of roofing assemblies of three buildings. As noted above, we observed no extensive wear or loss of roof granulars that would warrant either a full strip and replacement or a targeted rehab of the roofing assemblies on the Row Homes at this time.
05 Gutters & Downspouts		25	2007	11	-9	5	3	1	EA	\$97,500.00	Y \$104	Observed Conditions/Recommended Actions: These components were replaced in 2013. Some locations were dented or damaged but appeared to be performing as intended. It is recommended the Association add routine maintenance tasks to their maintenance plan thelp prolong the life of these components and to ensure they continue perform as designed.
Sub-Section #4: Misc. Exterior Cladding Assemblies												
06 Lighting: Wall-Mounted Lamp, (Rear Elevation)	Proto Pendino	20	2013	5	-12	3	25	65	EA	\$75	N \$4	Observed Conditions/Recommended Actions: Limited quantities observed. Funding plan assumes these components will be replaced an "As-Needed" basis and will take place over an extended period of time.
07 Electrical Outlet		20	2013	5	-12	3	25	130	EA	\$100	N \$13	Observed Conditions/Recommended Actions: No access to the rear elevations was provided during our field observations. Funding plan assumes these components will be replaced on an "As-Needed" basis and will take place over an extended period of time.
08 Hose Bib		20	2007	11	-6	3	25	130	EA	\$100	N \$13	Observed Conditions/Recommended Actions: Limited quantities observed. Funding plan assumes these components will be replaced an "As-Needed" basis and will take place over an extended period of time.

^{*} Quantity of years needed or scheduled to complete the renewal process.

^{**} Renewal costs listed are the current values should the scheduled replacement take place the year this RS was completed...

Arbor Terrace Community - Rowhomes

Scenario Two - Table 3: Shared Common Elements List - Replacement Cost Estimates Are Based On Current Year Dollars, (2018)

Scenario Two - Table 3: Shared Common Elements List - Replacement Cost Estimate	S Are based On Current Tear bo	Estimated	Assumed		Adjustment To	Estimated Time				F	Add 3rd Party	Current	
Item # Item Description	Component Caption	Life Expectancy	Year of	Present Age as of 2017	Estimated Life	To Firet	Number of Annual Phases *	Quantity	Units of Measure	Estimated Unit Cost	Consultant Foo	Estimated Replacement Costs **	Comments/Recommendations
SHARED COMMON ELEMENTS #2: FENCING													
Sub-Category #2: Wood Fencing													
09 6' Cedar Fence, (Good Neighbor Style)		15	2016	2	0	13	1	1,464	Ln. Ft.	\$41	N	\$60,020	Observed Conditions/Recommended Actions: This component was just replaced in 2016 and appear to be in good condition. Note: The Association has instructed that they will no longer be refinishing the wood fencing located throughout the community. However they intend to add a maintenance task for regular scheduled cleaning. Funds required for this task will be drawn from the Operating Budget. Estimated unit costs were provide by the Association's contractor, (Charter Construction).
SHARED COMMON ELEMENTS #3: ASPHALT ROADWAYS													
Sub-Section #1: Asphalt Roadways - Slurry Seal, (Maintenance Task)													
10 Tract A	Proto Parkins	10	2007	11	3	3	1	1,730	Sq. Ft.	\$0.35	N	\$610	Per the Association's direction, the renewal costs for this component will be addressed through the "All Lots" funding plan. Observed Conditions/Recommended Actions: These components were recently replaced and appear to be in good condition. No action required at this time, (per the 2018/2019 RS Update, Lvl 2) Note: Estimated costs also includes restriping and other painted marking on the surfaces the asphalt.
11 Tract D	Proto Pendind	10	2007	11	3	3	1	1,794	Sq. Ft.	\$0.35	N	\$630	The Row Homes are responsible for 19% of the renewal costs for this component. The remaining 81% are covered within the Tamarack Homes RS. Observed Conditions/Recommended Actions: These components were recently replaced and appear to be in good condition. No action required at this time, (per the 2018/2019 RS Update, LvI 2) Note: Estimated costs also includes restriping and other painted marking on the surfaces the asphalt.
Sub-Section #2: Asphalt Roadways - Re-Top Application, (Renewal Task)													
12 Tract A	Proto Pendino	30	2007	11	0	19	1	1,730	Sq. Ft.	\$3.00	N	\$5,190	The Row Homes are responsible for 23% of the renewal costs for this component. The remaining 77% are covered within the Tamarack Homes RS. Observed Conditions/Recommended Actions: Appears to be in good condition. No action required at this time, (per the 2018/2019 RS Update, Lvl 2). Note: Renewal scope includes full demo or grinding of asphalt surface and apply new layers. It is recommended the Association consider hiring a Consultant/Engineer who specialize in this field during the renewal period for this component.
13 Tract D	Photo Pandind	30	2007	11	0	19	1	1,794	Sq. Ft.	\$3.00	N	\$5,380	The Row Homes are responsible for 19% of the renewal costs for this component. The remaining 81% are covered within the Tamarack Homes RS. Observed Conditions/Recommended Actions: Appears to be in good condition. No action required at this time, (per the 2018/2019 RS Update, Lvl 2). Note: Renewal scope includes full demo or grinding of asphalt surface and apply new layers. It is recommended the Association consider hiring a Consultant/Engineer who specialize in this field during the renewal period for this component.

^{*} Quantity of years needed or scheduled to complete the renewal process.

^{**} Renewal costs listed are the current values should the scheduled replacement take place the year this RS was completed...

Arbor Terrace Community - Rowhomes

Scenario Two - Table 3: Shared Common Elements List - Replacement Cost Estimates Are Based On Current Year Dollars, (2018)

Item#	Item Description	Component Caption	Estimated Life Expectancy	Assumed Year of Acquisition	Present Age as of 2017	Adjustment To Estimated Life Expectancy	Estimated Time To First Replacement	Number of Annual Phases *	Quantity	Units of Measure	Estimated Unit Cost	Add 3rd Party Consultant Fee (Y/N)	Current Estimated Replacement Costs **	Comments/Recommendations
	HARED COMMON ELEMENTS #4: PROFESSIONAL SERVICES													
Sub-Ca	egory #1: Building Envelope Assessments													
14	Building Envelope Condition Assessment - Three Year Review	41/P	3	2013	5	4	4	1	1	EA	\$3,500	N	\$3,500	It is recommended the Association schedule once every three years a visual only building envelope assessment of the exterior wall assemblies for the townhomes.
15	Building Envelope Condition Assessment - Six Year Performance Review	ME	6	2013	5	0	1	1	1	EA	\$10,000	N	\$10,000	MH recommends that the Association hire a licensed architectural engineering firm that specialize in the field of exterior cladding systems to conduct comprehensive condition assessment every six years. Scope should include exploratory openings as part of this assessment to see the existing conditions of the underlying wall assembles. Costs provided include contractor fees that will be required to assist with the opening and closing of the areas observed as part of the exploratory opening phase typically included as part of this kind of an assessment.

* Quantity of years needed or scheduled to complete the renewal process.

^{**} Renewal costs listed are the current values should the scheduled replacement take place the year this RS was completed...

APPENDIX H

TABLE 4: DETAILED CASH FLOW, (SCENARIO TWO) ROWHOMES

The "Detailed Cash-Flow" table is generated based on the estimated values established by "Table 3: Shared Common Elements List, (Scenario Two)", (See Appendix G) and is designed to anticipate the necessary cash flow for each year over the 30-year period of this study. The estimated renewal costs listed within Table 4 includes the assumed rate of inflation, (2%) for each of the years leading up to the date of replacement.

Optional Yearly Contribution, (Year One): \$	63,960	Monthly Contribution, (Per Unit "Average" For Year One): \$82													
Starting Balance	\$191,000	\$257,190	\$328,190	\$410,152	\$490,294	\$568,725	\$410,483	\$245,548	\$62,209	\$152,913	\$244,494	\$344,244	\$434,849	\$526,329	\$526,050
Total Expenses inflated at 2% annually	\$0	\$10,200	\$0	\$2,627	\$5,126	\$254,195	\$259,278	\$275,951	\$1,447	\$1,476	\$5,772	\$1,536	\$1,567	\$93,780	\$1,630
Interest at 1% annually	\$2,230	\$2,841	\$3,602	\$4,408	\$5,197	\$4,800	\$3,192	\$1,459	\$999	\$1,906	\$2,857	\$3,876	\$4,782	\$5,236	\$5,694
Annual Reserve Contribution	\$63,960	\$63,960	\$63,960	\$63,960	\$63,960	\$76,752	\$76,752	\$76,752	\$76,752	\$76,752	\$88,265	\$88,265	\$88,265	\$88,265	\$88,265
Other Contributions Via Special Assessment, (Per the direction of the Assocition)		\$14,400	\$14,400	\$14,400	\$14,400	\$14,400	\$14,400	\$14,400	\$14,400	\$14,400	\$14,400				
Ending Balance	\$257,190	\$328,190	\$410,152	\$490,294	\$568,725	\$410,483	\$245,548	\$62,209	\$152,913	\$244,494	\$344,244	\$434,849	\$526,329	\$526,050	\$618,378
Fiscal Year	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
Calendar Year	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
SHARED COMMON ELEMENTS #1: BUILDING ENVELOPE COMPONENTS															
Sub-Section #1: Exterior Cladding Assemblies, (Components "NOT" Replaced During The 2013 Rehab Project)															
01 Exterior Wall Assemblies - Total Renewal Costs - Deduct Downspouts and gutters															
Sub-Section #2: Exterior Cladding Assemblies															
02 Exterior Wall Assemblies - Siding & Trim Details, (Replaced in 2013)															
03 Exterior Finishes: Paint & Sealant, (Caulking)						\$57,412	\$58,560	\$59,732							
Sub-Section #3: Roofing Assemblies															
04 Roofing System, (Asphaltic Roof Shingles)						\$157,022	\$160,163	\$163,366							
05 Gutters & Downspouts						\$38,396	\$39,164	\$39,947							
Sub-Section #4: Misc. Exterior Cladding Assemblies															
06 Lighting: Wall-Mounted Lamp, (Rear Elevation)				\$207	\$211	\$216	\$220	\$224	\$229	\$233	\$238	\$243	\$248	\$253	\$258
07 Electrical Outlet				\$552	\$563	\$574	\$586	\$597	\$609	\$621	\$634	\$647	\$659	\$673	\$686
08 Hose Bib				\$552	\$563	\$574	\$586	\$597	\$609	\$621	\$634	\$647	\$659	\$673	\$686
SHARED COMMON ELEMENTS #2: FENCING															
Sub-Category #2: Wood Fencing															
09 6' Cedar Fence, (Good Neighbor Style)														\$77,642	
SHARED COMMON ELEMENTS #3: ASPHALT ROADWAYS															
Sub-Section #1: Asphalt Roadways - Slurry Seal, (Maintenance Task)															
10 Tract A				\$647										\$789	
11 Tract D				\$669										\$815	
Sub-Section #2: Asphalt Roadways - Re-Top Application, (Renewal Task)															
12 Tract A															
13 Tract D															
SHARED COMMON ELEMENTS #4: PROFESSIONAL SERVICES															
Sub-Category #1: Building Envelope Assessments															
14 Building Envelope Condition Assessment - Three Year Review					\$3,789						\$4,266				
15 Building Envelope Condition Assessment - Six Year Performance Review		\$10,200						\$11,487						\$12,936	
															i

Optional Yearly Contribution, (Year One): \$	Monthly Contribution, (Per Unit "Average" For Year One): \$82														
Starting Balance	\$618,378	\$428,369	\$225,667	\$19,683	\$120,118	\$191,407	\$303,690	\$417,058	\$526,085	\$641,601	\$758,234	\$784,988	\$826,742	\$867,124	\$885,925
Total Expenses inflated at 2% annually	\$296,722	\$307,461	\$308,709	\$1,764	\$31,766	\$1,835	\$1,872	\$7,321	\$1,948	\$1,987	\$103,744	\$89,085	\$90,866	\$112,740	\$4,149
Interest at 1% annually	\$5,208	\$3,254	\$1,221	\$696	\$1,550	\$2,463	\$3,586	\$4,692	\$5,809	\$6,964	\$7,678	\$8,019	\$8,427	\$8,722	\$9,453
Annual Reserve Contribution	\$101,505	\$101,505	\$101,505	\$101,505	\$101,505	\$111,655	\$111,655	\$111,655	\$111,655	\$111,655	\$122,820	\$122,820	\$122,820	\$122,820	\$122,820
Other Contributions Via Special Assessment, (Per the direction of the Assocition)															
Ending Balance	\$428,369	\$225,667	\$19,683	\$120,118	\$191,407	\$303,690	\$417,058	\$526,085	\$641,601	\$758,234	\$784,988	\$826,742	\$867,124	\$885,925	\$1,014,050
Fiscal Year	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
Calendar Year	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047
SHARED COMMON ELEMENTS #1: BUILDING ENVELOPE COMPONENTS															
Sub-Section #1: Exterior Cladding Assemblies, (Components "NOT" Replaced During The 2013 Rehab Project)															
01 Exterior Wall Assemblies - Total Renewal Costs - Deduct Downspouts and gutters	\$225,074	\$229,576	\$234,167												
Sub-Section #2: Exterior Cladding Assemblies															
02 Exterior Wall Assemblies - Siding & Trim Details, (Replaced in 2013)															
03 Exterior Finishes: Paint & Sealant, (Caulking)	\$69,985	\$71,385	\$72,813								\$85,312	\$87,018	\$88,758		
Sub-Section #3: Roofing Assemblies															
04 Roofing System, (Asphaltic Roof Shingles)															
05 Gutters & Downspouts															
Sub-Section #4: Misc. Exterior Cladding Assemblies															
06 Lighting: Wall-Mounted Lamp, (Rear Elevation)	\$263	\$268	\$273	\$279	\$284	\$290	\$296	\$302	\$308	\$314	\$320	\$327	\$333	\$340	\$347
07 Electrical Outlet	\$700	\$714	\$728	\$743	\$758	\$773	\$788	\$804	\$820	\$836	\$853	\$870	\$888	\$905	\$923
08 Hose Bib	\$700	\$714	\$728	\$743	\$758	\$773	\$788	\$804	\$820	\$836	\$853	\$870	\$888	\$905	\$923
SHARED COMMON ELEMENTS #2: FENCING															
Sub-Category #2: Wood Fencing															
09 6' Cedar Fence, (Good Neighbor Style)														\$104,496	
SHARED COMMON ELEMENTS #3: ASPHALT ROADWAYS															
Sub-Section #1: Asphalt Roadways - Slurry Seal, (Maintenance Task)															
10 Tract A															\$961.91
11 Tract D															\$993.45
Sub-Section #2: Asphalt Roadways - Re-Top Application, (Renewal Task)															
12 Tract A					\$7,561										
13 Tract D					\$7,838										
SHARED COMMON ELEMENTS #4: PROFESSIONAL SERVICES															
Sub-Category #1: Building Envelope Assessments															
14 Building Envelope Condition Assessment - Three Year Review		\$4,805						\$5,411						\$6,094	
15 Building Envelope Condition Assessment - Six Year Performance Review					\$14,568						\$16,406				

APPENDIX I FIVE YEAR EXPENDITURE OUTLOOK, (SCENARIO TWO) ROWHOMES

Five Year Outlook Sheet, (Scenario 2)

	2018	
-	Nothing Scheduled	-

2019								
15	Building Envelope Condition Assessment - Six Year Performance Review	\$10,200						
		\$10,200						

	2020	
-	Nothing Scheduled	-

	2021							
06	Lighting: Wall-Mounted Lamp, (Rear Elevation)	\$207						
07	Electrical Outlet	\$552						
08	Hose Bib	\$552						
10	Tract A	\$647						
11	Tract D	\$669						
		\$2,627						

	2022							
06	Lighting: Wall-Mounted Lamp, (Rear Elevation)	\$211						
07	Electrical Outlet	\$563						
08	Hose Bib	\$563						
14	Building Envelope Condition Assessment - Three Year Review	\$3,789						
		\$5,126						

6. FUNDING ALTERNATIVES - TAMARACK SFH

Summary of Data & Results

Property Name Entity Name Current Date Year Built, (Conversion Year) Starting Year, (Forecasted Fiscal Year) Dollar Year, (Current Fiscal Year) Fiscal Year Start Date	Arbor Terrace Commu	unity - Tamarack SFH Arbor Terrace HOA June 14, 2018 2007 2018 2018 July 1, 2018
Fiscal Year End Date Assumed Inflation Rate Earned Interest Rate Estimated Starting Balance Number of Units		June 30, 2019 2.00% 1.00% (\$25,000) 45
Approved Funding Plan		
Current Yearly Contribution:	\$	18,900
Monthly Contribution, (Per Unit "Average" For Year One):	\$	35
Lowest Annual Closing Balance	\$	(6,100)
Largest Annual Closing Balance	\$	325,375
30-Year Closing Balance	\$	226,522
Consulting Allowance		7%

Page 58 of 74

□ Asphalt Roadways \$100,939 ■ Wood Fencing \$211,658 □ Metal Fencing \$277,077 Arbor Terrace Community - Tamarack SFH - Funding Graph #1 - FINAL Percentage of Anticipated Expenditures By Groups (Groups are formed by multiple factors such as similar renewal timelines & common functions) 47%

Scenario 1: Current Funding Path's 30 Year Ending Balance: \$226,522 9₄₀ A O c₃₀ Arbor Terrace Community - Tamarack SFH - Funding Graph #2 - FINAL 0402 8507 ₀607 Scenario Comparison *SOZ c₅₀₂ 0502 80/2 ₉% * * OS 200 0202 8/05 \$250,000 \$150,000 \$100,000 (\$50,000)\$350,000 \$50,000 \$0 \$300,000 \$200,000 Yearly Ending Balance for Each Scenario

Tamarack SFH - Approved Funding Plan

The following funding plan has been designed and approved by the Association's Board of Directors for this year's update, (2018/2019 Fiscal Year). The starting account balance within the reserves at year one will be approximately (\$25,000) with an annual contribution of \$18,900, (figures were provided by Ms. Amy Boyle). All rate increases to the reserve's annual contributions have also been established by the Association's Board of Directors, (BOD).

Analysis

Apart from year one, (fiscal year 2018/2019) the amount of funds within the reserve's account will maintain a positive balance for 29 years. This is contingent on the Association following the funding plan and the scheduled annual increases to the contributions that they have established within this RS over this same period of time. This will also be impacted on how well they maintain and care for their shared common elements.

The chart below shows the three largest renewal periods over the 30-year scope set by this study:

<u>Periods</u>	Major Renewal Task	Est. Cost
2030 – 2033	Metal & Wood Fence Renewals	\$305K
2037/2038	Asphalt Re-Top	\$80K
2047/2048	Wood Fence Renewal	\$120K

Please note, that the forecasted repairs and replacements do not represent a fixed schedule for any given element or component reviewed. Such repairs or replacements may be required sooner or later than we have anticipated. It should also be noted that these repairs and replacements may not all take place within one year's time and may not be required at all. However, it is prudent to budget for such repairs since failure of some components is somewhat unpredictable.

Results

With the exception of the negative balance of (\$6,100) at year one, this funding plan as approved by the Association will maintain an amount greater than \$0, (Baseline Funding) over the 30-year term set by this RS. With no expenditures scheduled to be drawn against the reserve account for the first three years of this funding plan, which will allow the Association to build up it's reserves in time to address all other future expenditures, MH can recommend this funding plan.


Annual contributions within this funding plan have been aligned with the list of shared common elements shown in Appendix J, Table 3, (assuming the expenditure is scheduled to be replaced by June 30, 2048). The ensuing two graphics, (Table 1 & Table 2) illustrate what the Association should anticipate over the next 30 years should they follow this funding path. For a detailed breakout of the anticipated cash flow for this funding plan see Appendix K, Table 4.

Arbor Terrace Community - Tamarack SFH Approved Funding Plan Table 1: Cash Flow Summary

Current Yearly Contribution:\$18,900Monthly Contribution, (Per Unit "Average" For Year One):\$35Assumed Interest Rate1.00%Assumed Inflation Rate2.00%Reserve's Starting Balance as of July 1, 2018(\$25,000)Reserve's Minimum Annual Ending Balance Within 30 Year Scope(\$6,100)

#	Year	Annual Opening Balance	Annual Contribution	Annual Rate Increase	Other Contributions	Estimated Annual Expenditures	Projected Earned Interest	Annual Closing Balance
1	2018/2019	(\$25,000)	\$18,900	40.0%	\$0	\$0	\$0	(\$6,100)
2	2019/2020	(\$6,100)	\$18,900	0.0%	\$0	\$0	\$34	\$12,834
3	2020/2021	\$12,834	\$18,900	0.0%	\$0	\$0	\$223	\$31,956
4	2021/2022	\$31,956	\$18,900	0.0%	\$0	\$32,632	\$251	\$18,475
5	2022/2023	\$18,475	\$18,900	0.0%	\$0	\$0	\$279	\$37,654
6	2023/2024	\$37,654	\$23,625	25.0%	\$0	\$0	\$495	\$61,774
7	2024/2025	\$61,774	\$23,625	0.0%	\$0	\$0	\$736	\$86,135
8	2025/2026	\$86,135	\$23,625	0.0%	\$0	\$0	\$979	\$110,739
9	2026/2027	\$110,739	\$23,625	0.0%	\$0	\$0	\$1,226	\$135,590
10	2027/2028	\$135,590	\$23,625	0.0%	\$0	\$0	\$1,474	\$160,689
11	2028/2029	\$160,689	\$29,531	25.0%	\$0	\$0	\$1,755	\$191,975
12	2029/2030	\$191,975	\$29,531	0.0%	\$0	\$0	\$2,067	\$223,573
13	2030/2031	\$223,573	\$29,531	0.0%	\$0	\$69,331	\$2,037	\$185,811
14	2031/2032	\$185,811	\$29,531	0.0%	\$0	\$78,673	\$1,612	\$138,282
15	2032/2033	\$138,282	\$29,531	0.0%	\$0	\$162,357	\$719	\$6,174
16	2033/2034	\$6,174	\$29,531	0.0%	\$0	\$0	\$209	\$35,915
17	2034/2035	\$35,915	\$29,531	0.0%	\$0	\$0	\$507	\$65,953
18	2035/2036	\$65,953	\$29,531	0.0%	\$0	\$0	\$807	\$96,291
19	2036/2037	\$96,291	\$29,531	0.0%	\$0	\$0	\$1,111	\$126,933
20	2037/2038	\$126,933	\$29,531	0.0%	\$0	\$76,759	\$1,033	\$80,738
21	2038/2039	\$80,738	\$29,531	0.0%	\$0	\$0	\$955	\$111,224
22	2039/2040	\$111,224	\$29,531	0.0%	\$0	\$0	\$1,260	\$142,016
23	2040/2041	\$142,016	\$29,531	0.0%	\$0	\$0	\$1,568	\$173,115
24	2041/2042	\$173,115	\$29,531	0.0%	\$0	\$38,792	\$1,685	\$165,539
25	2042/2043	\$165,539	\$29,531	0.0%	\$0	\$0	\$1,803	\$196,873
26	2043/2044	\$196,873	\$29,531	0.0%	\$0	\$0	\$2,116	\$228,521
27	2044/2045	\$228,521	\$29,531	0.0%	\$0	\$0	\$2,433	\$260,485
28	2045/2046	\$260,485	\$29,531	0.0%	\$0	\$0	\$2,753	\$292,769
29	2046/2047	\$292,769	\$29,531	0.0%	\$0	\$0	\$3,075	\$325,375
30	2047/2048	\$325,375	\$29,531	0.0%	\$0	\$131,130	\$2,746	\$226,522
						\$589,674		

Arbor Terrace Community - Tamarack SFH Approved Funding Plan Table 2: Cash Flow Chart



APPENDIX J

TABLE 3: SHARED COMMON ELEMENTS LIST - TAMARACK SFH

This table provides a list of the shared common elements that includes information such as each component's quantities, dates of initial installation or renewal, and estimated unit costs. In addition, this table includes a list of brief comments or recommendations for each corresponding item. MH recommends that close attention be maintained for systems that have an "elevated maintenance" requirement. These components are typically exposed to conditions where they are unlikely to fulfill their usual service life. However it should be noted that in some instances a heightened maintenance plan can maximize the component's serviceable life span. Where a specific material, component or assembly could not be verified during our review, we have assumed the components are suitable for their intended use. Estimated replacement costs are based on current year dollars, (2018).

Arbor Terrace Community - Tamarack SFH

Table 3: Shared Common Elements List - Replacement Cost Estimates Are Based On Current Year Dollars, (2018)

Table 3: Shared Common Elements List - Replacement Cost Estimates Item # Item Description Item Descri	Component Caption	Estimated Life Expectancy	Assumed Year of Acquisition	Present Age as of 2018	Estimated Lif	e Estimated Time To First Replacement	Number of Annual Phases *	Quantity	Units of Measure	Estimated Unit Costs	Add 3rd Party Consultant Fee (Y/N) Current Estimated Replacement Costs **	Comments/Recommendations
SHARED COMMON ELEMENTS #1: FENCING												
Sub-Category #1: Metal Fencing												
01 42" Metal Fencing & Gates @ Front Elev Refinishing, (Maintenance Task)		10	2013	5	-2	3	1	3,280	Ln. Ft.	\$7.50	N \$24,600	Observed Conditions/Recommended Actions: Early signs of corrosion were identified at selection locations where paint finish was either blistering or had been fully removed. It is recommended these areas be treated and refinished within the next year to prevent further deterioration. Note: The Association has instructed that the scheduled renewal date for this line item will take place 10 years after the metal railing has been replaced, (See Item #02 for scheduled replacement of the metal railing). Estimated values are based on a field applied finish.
02 42" Metal Fencing & Gates @ Front Elev Replacement, (Renewal Task)	Photo Balding	25	2007	11	-2	12	3	3,280	Ln. Ft.	\$50	N \$164,000	Observed Conditions/Recommended Actions: Early signs of corrosion were identified at selection locations where paint finish was either blistering or had been fully removed. It is recommended these areas be treated and refinished within the next year to prevent further deterioration. Note: The Association has instructed that the scheduled renewal date for this line item will take place in 2030.
Sub-Category #2: Wood Fencing												
03 6' Cedar Fence w/12" Vertical Lattice Top		15	2017	1	0	14	1	683	Ln. Ft.	\$41.50	N \$28,340	Observed Conditions/Recommended Actions: This component was just replaced in 2017. Note: The Association has instructed that they will no longer be refinishing the wood fencing located throughout the community. However they intend to add a maintenance task for regular scheduled cleaning. Funds required for this task will be drawn from the Operating Budget. Estimated unit costs were provided by the Association's fencing contractor, (Charter Construction)
04 6' Cedar Fence w/Top Cap Privacy)		15	2017	1	0	14	1	767	Ln. Ft.	\$39.00	N \$29,910	Observed Conditions/Recommended Actions: This component was just replaced in 2017. Note: The Association has instructed that they will no longer be refinishing the wood fencing located throughout the community. However they intend to add a maintenance task for regular scheduled cleaning. Funds required for this task will be drawn from the Operating Budget. Estimated unit costs were provided by the Association's fencing contractor, (Charter Construction)
05 Cedar Fencing Gates		15	2017	1	0	14	1	45	EA	\$225.00	N \$10,130	Observed Conditions/Recommended Actions: This component was just replaced in 2017. Note: The Association has instructed that they will no longer be refinishing the wood fencing located throughout the community. However they intend to add a maintenance task for regular scheduled cleaning. Funds required for this task will be drawn from the Operating Budget. Estimated unit costs were provided by the Association's fencing contractor, (Charter Construction)

^{*} Quantity of years needed or scheduled to complete the renewal process.

^{**} Renewal costs listed are the current values should the scheduled replacement take place the year this RS was completed...

Arbor Terrace Community - Tamarack SFH

Table 3: Shared Common Elements List - Replacement Cost Estimates Are Based On Current Year Dollars, (2018)

Table 3: Shared Common Elements List - Replacement Cost Estimates Are Based O Item # Item Description	Component Caption	Estimated Life Expectancy	Assumed Year of Acquisition	Present Age as of 2018	Estimated Life	Estimated Time To First Replacement	Number of Annual Phases *	Quantity	Units of Measure	Estimated Unit Costs	Consultant Fee	Current Estimated Replacement Costs **	Comments/Recommendations
SHARED COMMON ELEMENTS #2: ASPHALT ROADWAYS													
Sub-Section #1: Asphalt Roadways - Slurry Seal, (Maintenance Task)													
06 Tract "A"	Proto Pending	10	2007	11	3	3	1	5,790	Sq. Ft.	\$0.35	N	\$2,030	The Tamarack SFH are responsible for 77% of the renewal costs for th component. The remaining 23% is covered within the Row Homes RS. Observed Conditions/Recommended Actions: These components were recently replaced and appear to be in good condition. No action require at this time, (per the 2018/2019 RS Update, Lvl 2)
07 Tract "C"	ProtoPending	10	2007	11	3	3	1	4,125	Sq. Ft.	\$0.35	N	\$1,440	The Tamarack SFH are responsible for 100% of the renewal costs for this component. Observed Conditions/Recommended Actions: These components were recently replaced and appear to be in good condition. No action require at this time, (per the 2018/2019 RS Update, Lvl 2)
08 Tract "D"	PhotoPandind	10	2007	11	3	3	1	7,646	Sq. Ft.	\$0.35	N	\$2,680	The Tamarack SFH are responsible for 81% of the renewal costs for this component. The remaining 19% is covered within the Row Homes RS. Observed Conditions/Recommended Actions: These components were recently replaced and appear to be in good condition. No action require at this time, (per the 2018/2019 RS Update, Lvl 2)
Sub-Section #2: Asphalt Roadways - Re-Top Application, (Renewal Task)													
09 Tract "A"	ProtoPending	30	2007	11	0	19	1	5,790	Sq. Ft.	\$3.00	N	\$17,370	The Tamarack SFH are responsible for 77% of the renewal costs for thi component. The remaining 23% is covered within the Row Homes RS. Observed Conditions/Recommended Actions: Appears to be in good condition. No action required at this time, (per the 2018/2019 RS Update, Lvl 2). Note: Renewal scope includes full demo or grinding of asphalt surface and apply new layers. It is recommended the Association consider hiring a Consultant/Engineer who specialize in this field during the renewal period for this component.
10 Tract "C"	Photo Panding	30	2007	11	0	19	1	4,125	Sq. Ft.	\$3.00	N	\$12,380	The Tamarack SFH are responsible for 100% of the renewal costs for this component. Observed Conditions/Recommended Actions: Appears to be in good condition. No action required at this time, (per the 2018/2019 RS Update, Lvl 2). Note: Renewal scope includes full demo or grinding of asphalt surface and apply new layers. It is recommended the Association consider hirir a Consultant/Engineer who specialize in this field during the renewal period for this component.
11 Tract "D"	PhotoPending	30	2007	11	0	19	1	7,646	Sq. Ft.	\$3.00	N	\$22,940	The Tamarack SFH are responsible for 81% of the renewal costs for thi component. The remaining 19% is covered within the Row Homes RS. Observed Conditions/Recommended Actions: Appears to be in good condition. No action required at this time, (per the 2018/2019 RS Update, Lvl 2). Note: Renewal scope includes full demo or grinding of asphalt surface and apply new layers. It is recommended the Association consider hirin a Consultant/Engineer who specialize in this field during the renewal period for this component.

^{*} Quantity of years needed or scheduled to complete the renewal process.

^{**} Renewal costs listed are the current values should the scheduled replacement take place the year this RS was completed...

APPENDIX K APPROVED FUNDING PLAN – TAMARACK SFH TABLE 4: DETAILED CASH FLOW

The "Detailed Cash-Flow" table is generated based on the estimated values established by "Table 3: Shared Common Elements List", (See Appendix J) and is designed to anticipate the necessary cash flow for each year over the 30-year period of this study. The estimated renewal costs listed within Table 4 includes the assumed rate of inflation, (2%) for each of the years leading up to the date of replacement.

Current Yearly Contribution: \$1	8,900		Monthly Con	tribution, (Per U	nit "Average" F	or Year One): \$3	5								
Starting Balance	(\$25,000)	(\$6,100)	\$12,834	\$31,956	\$18,475	\$37,654	\$61,774	\$86,135	\$110,739	\$135,590	\$160,689	\$191,975	\$223,573	\$185,811	\$138,282
Total Expenses inflated at 2% annually	\$0	\$0	\$0	\$32,632	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$69,331	\$78,673	\$162,357
Interest at 1% annually	\$0	\$34	\$223	\$251	\$279	\$495	\$736	\$979	\$1,226	\$1,474	\$1,755	\$2,067	\$2,037	\$1,612	\$719
Annual Reserve Contribution	\$18,900	\$18,900	\$18,900	\$18,900	\$18,900	\$23,625	\$23,625	\$23,625	\$23,625	\$23,625	\$29,531	\$29,531	\$29,531	\$29,531	\$29,531
Other Contribution															
Ending Balance	(\$6,100)	\$12,834	\$31,956	\$18,475	\$37,654	\$61,774	\$86,135	\$110,739	\$135,590	\$160,689	\$191,975	\$223,573	\$185,811	\$138,282	\$6,174
Fiscal Year	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
Calendar Year	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032
SHARED COMMON ELEMENTS #1: FENCING															
Sub-Category #1: Metal Fencing															
01 42" Metal Fencing & Gates @ Front Elev Refinishing, (Maintenance Task)				\$26,106											
02 42" Metal Fencing & Gates @ Front Elev Replacement, (Renewal Task)													\$69,331	\$70,717	\$72,132
Sub-Category #2: Wood Fencing															
03 6' Cedar Fence w/12" Vertical Lattice Top															\$37,394
04 6' Cedar Fence w/Top Cap Privacy)															\$39,466
05 Cedar Fencing Gates															\$13,366
SHARED COMMON ELEMENTS #2: ASPHALT ROADWAYS															
Sub-Section #1: Asphalt Roadways - Slurry Seal, (Maintenance Task)															
06 Tract "A"				\$2,154										\$2,626	
07 Tract "C"				\$1,528										\$1,863	
08 Tract "D"				\$2,844										\$3,467	
Sub-Section #2: Asphalt Roadways - Re-Top Application, (Renewal Task)															
09 Tract "A"															
10 Tract "C"															
11 Tract "D"															

Arbor Terrace Community - Tamarack SFH Approved Funding Plan

Table 4: Detailed Cash Flow

Curre	Current Yearly Contribution: \$18,900				Monthly Contribution, (Per Unit "Average" For Year One): \$35												
	Starting Balance	\$6,174	\$35,915	\$65,953	\$96,291	\$126,933	\$80,738	\$111,224	\$142,016	\$173,115	\$165,539	\$196,873	\$228,521	\$260,485	\$292,769	\$325,375	
Total Expense	es inflated at 2% annually	\$0	\$0	\$0	\$0	\$76,759	\$0	\$0	\$0	\$38,792	\$0	\$0	\$0	\$0	\$0	\$131,130	
	Interest at 1% annually	\$209	\$507	\$807	\$1,111	\$1,033	\$955	\$1,260	\$1,568	\$1,685	\$1,803	\$2,116	\$2,433	\$2,753	\$3,075	\$2,746	
Ann	ual Reserve Contribution	\$29,531	\$29,531	\$29,531	\$29,531	\$29,531	\$29,531	\$29,531	\$29,531	\$29,531	\$29,531	\$29,531	\$29,531	\$29,531	\$29,531	\$29,531	
	Other Contribution																
	Ending Balance	\$35,915	\$65,953	\$96,291	\$126,933	\$80,738	\$111,224	\$142,016	\$173,115	\$165,539	\$196,873	\$228,521	\$260,485	\$292,769	\$325,375	\$226,522	
	Fiscal Year	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	
	Calendar Year	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	
SHARED COMMON ELEMENTS #1: FENCING																	
Sub-Category #1: Metal Fencing																	
01 42" Metal Fencing & Gates @ Front Elev Refinishing, (Maintenance Task)										\$38,792							
02 42" Metal Fencing & Gates @ Front Elev Replacement, (Renewal Task)																	
Sub-Category #2: Wood Fencing																	
03 6' Cedar Fence w/12" Vertical Lattice Top																\$50,327	
04 6' Cedar Fence w/Top Cap Privacy)																\$53,116	
05 Cedar Fencing Gates																\$17,989	
SHARED COMMON ELEMENTS #2: ASPHALT ROADWAYS																	
Sub-Section #1: Asphalt Roadways - Slurry Seal, (Maintenance Task)																	
06 Tract "A"																\$3,201	
07 Tract "C"																\$2,271	
08 Tract "D"																\$4,226	
Sub-Section #2: Asphalt Roadways - Re-Top Application, (Renewal Task)																	
09 Tract "A"						\$25,305											
10 Tract "C"						\$18,035											
11 Tract "D"						\$33,419											

APPENDIX L FIVE YEAR EXPENDITURE OUTLOOK – TAMARACK SFH

	2018	
-	Nothing Scheduled	-

	2019	
-	Nothing Scheduled	-

	2020	
-	Nothing Scheduled	-

	2021						
01	42" Metal Fencing & Gates @ Front Elev Refinishing, (Maintenance Task)	\$26,106					
06	Tract "A"	\$2,154					
07	Tract "C"	\$1,528					
08	Tract "D"	\$2,844					
		\$32,632					

	2022	
-	Nothing Scheduled	-

7. SUMMARY

Morrison Hershfield has reviewed and assessed the reserve requirements for the Arbor Terrace Homeowners Association in accordance with the scope of services indicated within our proposal and the "Limitations" outlined in Appendix M of this report.

The following table summarizes the results of the study:

Community Entity	Estimated Annual Contribution*	Estimated "Average Monthly Contribution Per Unit*
All Lots	\$28,800	\$15
Rowhomes, (Scenario 1 & 2)	\$63,960	\$82
Tamarack SFH	\$18,900	\$35

^{*} Financial figures are for year one of this study, July 1, 2018 to June 30, 2019

Our calculations of the accumulated funds within the reserve's account include the interest earned per the estimated rates approved by the Association.

The RS is a dynamic document that will change over time as repairs and/or replacements are carried out for each of the shared common elements included within this RS, as well as the ever-changing interest and inflation rates that affect our economy. As such, regular updates to the available reserve funds, including visual reviews of the shared common elements are necessary to re-assess the financial planning needs of the Association. MH also recommends that the Board of Directors review local and state laws, the Association's governing documents, as well as their community's goals and objectives in relationship to their investment decisions. It is also recommended that the Association utilize the services of a financial planner who can implement an investment strategy to maximize the rate of return on the accumulated reserve funds. This will put the Association in a proactive position to plan for future replacement work prior to the common elements reaching a fully deteriorated condition, which may result in less expensive repair costs.

The annual contributions to the reserve account have been established by the Board of Directors.

Sincerely, Morrison Hershfield Corporation

Bryan M. Costa, PE
Principal, Senior Building Science Consultant
U.S. Building Consultation
BCosta@morrisonhershfield.com

APPENDIX M LIMITATIONS

This report is intended for the sole use of the client indicated above and must not be distributed to, or used by, others without our knowledge. It is based on the documents and information provided to us and the findings at the time of our on-site review.

It is a basic assumption that any correspondence, material, data, evaluations and reports furnished by others are free of latent deficiencies or inaccuracies except for apparent variances discovered during the completion of this report.

Unless specifically noted in this report, no testing, verification of operation of systems, review of concealed elements, intrusive openings, opening of system components for internal inspection, detailed analysis or design calculations were conducted, nor were they within the scope of this review.

Some of the findings herein are based on a random sampling visual review of the surface conditions, discussions with the Board of Directors and/or their designated representatives, and review of relevant documents. Observations were made only of those areas that were readily accessible during our review. Deficiencies existing but not recorded in this report were not apparent given the level of study undertaken. Unless otherwise indicated in this report, components are assumed to be suitable for their intended use and are being used under normal service conditions. Finally, for this year's update, we have not undertaken a physical review of subsurface conditions or concealed structural systems.

It is possible that unexpected conditions may be encountered at buildings/facilities that have not been explored within the scope of this report. Should such an event occur, MH should be notified in order that we may determine if modifications to our conclusions are necessary.

In issuing this report, MH does not assume any of the duties or liabilities of the designers, builders or owners of the subject property. Owners, prospective purchasers, tenants or others who use or rely on the contents of this report do so with the understanding as to the limitations of the documents reviewed and the general visual review undertaken, and understand that MH cannot be held liable for damages they may suffer in respect to the purchase, ownership, or use of the subject property.

Professional judgment was exercised in gathering and analyzing the information obtained and in the formulation of the conclusions. Like all professional persons rendering advice, we do not act as insurers of the conclusions we reach, but we commit ourselves to care and competence in reaching those conclusions. No warranties, either expressed or implied, are made.